





report date: 2024-03-28

### General information

Make	CITROEN
Model	XSARA PICASSO LX 16V PICASSO E4
Colour	Blue
Year of manufacture	2006
Top speed	112 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	172 g/km
CO2 label	Н



CarCheck.co.uk page 1/13




# Internet history

### Entry 1

Date 2022-04-04

Pictures 9









source: cargurus.co.uk

CarCheck.co.uk page 2/13



B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-07-06
MOT pass rate	94 %
MOT passed	15
Failed MOT tests	1
Total advice items	10
Total items failed	2

MOT #16	2023-07-01 07:05
MOT test number	886913095904
Result	<b>✓</b> Passed
Next expiry date	2024-07-06
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #15	2022-07-07 09:59
MOT test number	392117390368
Result	<b>✓</b> Passed

MOT #14	2021-03-22 13:57
MOT test number	530745839066
Result	✓ Passed
Advice Power steering component has slight seepage from a component (2.1.5 (a))	

MOT #13		2020-03-13 14:32
MOT test	number	119397708584
Result		<b>✓</b> Passed
Advice	Power steering component has slight seepage from a component sensor /switc	th (2.1.5 (a))

CarCheck.co.uk page 3/13



MOT #12 2019-03-26 09:35

**MOT test number** 940511063708

Result \( \sqrt{Passed} \)

**Advice** Power steer

Power steering component has slight seepage from a component (2.1.5 (a))

**MOT #11** 2018-03-16 14:58

MOT test number 751344306728

**Advice** Nearside Front Tyre worn close to the legal limit outer edge (4.1.E.1)

Advice Offside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt

(2.2.C.1c)

**MOT #10** 2017-03-29 09:26

**MOT test number** 404490112935

**Result** ✓ Passed

MOT #9 2016-03-09 10:28

MOT test number 466915521410

**Result** ✓ Passed

MOT #8 2015-03-17 15:18

**MOT test number** 699206975007

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

CarCheck.co.uk page 4/13



BF06JPY

report date: 2024-03-28

MOT #7 2015-03-17 10:31

**MOT test number** 976236775004

**Result** X Failed

**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #6 2014-03-26 10:22

MOT test number 376025684067

Result Passed

MOT #5 2013-03-13 10:37

**MOT test number** 647742373096

**Result** ✓ Passed

MOT #4 2012-03-12 10:18

**MOT test number** 256352372049

MOT #3 2011-03-15 10:36

**MOT test number** 189394571009

**Result** ✓ Passed

MOT #2 2010-03-20 11:41

**MOT test number** 584099670086

CarCheck.co.uk page 5/13



MOT #1 2009-03-18 10:28 MOT test number 183487479030

CarCheck.co.uk page 6/13



## Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	6 July 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



## Owner history

•	
For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	
HARMAN CO. C.	
***************************************	
***************************************	
THE PARTY OF THE P	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	UK NE
Finds since	
Current registration	NK NK
Finds since	
	More info >
	11010111110

CarCheck.co.uk page 10/13



#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



# Mileage check

Registration #18

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-03-27
Last registration	2023-07-01
Complete history	See info



Registration #1	2006-03-27	10 mi
Registration #2	2009-03-18	15.781 mi
Registration #3	2010-03-20	21.667 mi
Registration #4	2011-03-15	27.095 mi
Registration #5	2012-03-12	31.601 mi
Registration #6	2013-03-13	36.079 mi
Registration #7	2014-03-26	40.609 mi
Registration #8	2015-03-17	44.494 mi
Registration #9	2015-03-17	44.501 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 12/13



Safety ratings

NCAP rating

**Video** <u>see crash video</u>

## Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg

## Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX6P2900022

CarCheck.co.uk page 13/13