






report date: 2024-03-28

General information

Make	BMW
Model	Z3 Z3 ROADSTER
Colour	Blue
Year of manufacture	1997
Top speed	128 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	180 Nm at 4.300 rpm
Engine capacity	1.895 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.2 mpg



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 3

Date 2021-07-27

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date	2021-06-23
------	------------

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-06-07

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

MOT history

MOT expiry date	2024-05-14
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	25
Total items failed	12

MOT #22	2023-04-26 16:14
MOT test number	333219884434
Result	✓ Passed
Next expiry date	2024-05-14

MOT #21	2022-04-26 09:05
MOT test number	161198783613
Result	✓ Passed
Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #20	2022-04-26 09:05
MOT test number	905472323029
Result	X Failed
Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #19	2021-05-15 08:17
MOT test number	130736770224
Result	✓ Passed

CarCheck.co.uk page 3/14



MOT #18 2021-05-15 08:17

MOT test number 968380810078

Result X Failed

Pass with rectification

Offside Windscreen washer jets misaligned and not providing sufficient fluid to

the windscreen (3.5 (a))

Pass with rectification Offside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #17 2019-05-07 11:32

MOT test number 989216846175

Result \(\sqrt{Passed} \)

MOT #16 2018-05-10 10:31

MOT test number 429463665658

Result ✓ Passed

MOT #15 2017-04-06 11:41

MOT test number 855216481187

Advice Offside Play in steering rack inner joint(s)

MOT #14 2016-04-14 10:58

MOT test number 832765406764

Result ✓ Passed

MOT #13 2015-04-15 11:42

MOT test number 125135005114

Result
✓ Passed

CarCheck.co.uk page 4/14



× Failed

MOT #12 2013-09-25 13:41

MOT test number 448168963209

Result \rightarrow Passed

Advice Brake hose has slight corrosion to ferrules (3.6.B.4e)

Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

Advice Brake hose has slight corrosion to ferrules (3.6.B.4e)

MOT #11 2012-10-10 11:29

MOT test number 355224082247

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

Notice Rear centre mounting perishing

MOT #10 2012-10-10 11:29

MOT test number 397424982400

Advice Front Brake pad(s) wearing thin (3.5.1g)

Notice Rear centre mounting perishing

Result

Pass with rectification Offside Headlamp aim too low (1.8)

Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #9 2011-10-13 16:58

MOT test number 397096581260

Result ✓ Passed

CarCheck.co.uk page 5/14



MOT #8 2011-10-11 16:34 **MOT test number** 597724481289

Result

X Failed

Fail Offside Front coil spring cracked (2.4.C.1a)

MOT #7 2010-09-04 11:24 **MOT test number** 382577240462 Result ✓ Passed

Advice

Front Brake pad(s) wearing thin (3.5.1g)

MOT #6 2009-08-20 17:06 **MOT test number** 773522739223 Result ✓ Passed

CarCheck.co.uk page 6/14



Advice

P54HJB

report date: 2024-03-28

MOT #5 2009-08-14 12:41 **MOT** test number 742716329201 Result × Failed Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3) Fail Windscreen washer provides insufficient washer liquid (8.2.3) Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1) Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4) Fail **Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2) Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3) Fail **Notice** Rear exhaust box rusted Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4		2008-05-06 13:09
MOT test	number	641787628124
Result		✓ Passed
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weaken	ned (3.5.1i)
Advice Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)		
Notice	Rattle from rear exhaust box	
Advice	Rear Exhaust has part of the system slightly deteriorated (7.1.1a)	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened	d (3.5.1i)
Advice movement	Offside Front Suspension arm rubber mounting deteriorated but not resulting (2.4.G.2)	ing in excessive

Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

CarCheck.co.uk page 7/14



report date: 2024-03-28

MOT #3 2007-05-04 16:31

MOT test number 970554127176

Result ✓ Passed

MOT #2 2007-05-02 15:00

MOT test number 780472627119

Result X Failed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #1 2006-05-05 18:35

MOT test number 742355526111

Result ✓ Passed

CarCheck.co.uk page 8/14



See MOT history

Tax & MOT check

Full MOT history



CarCheck.co.uk page 9/14



report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/14



Owner history

e when misterly	
For how long did the current and previous owner(s) have this BMW? How many owners defined the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	UK ZIN
Plate since	
Current registration	OK SILV
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	1997-12-31
Last registration	2023-04-26
Complete history	See info



Registration #1	1997-12-31	23 mi
Registration #2	2006-05-05	46.870 mi
Registration #3	2007-05-02	56.583 mi
Registration #4	2007-05-04	56.583 mi
Registration #5	2008-05-06	66.397 mi
Registration #6	2009-08-14	77.663 mi
Registration #7	2009-08-20	77.663 mi
Registration #8	2010-09-04	85.212 mi
Registration #9	2011-10-11	90.324 mi
Registration #10	2011-10-13	90.331 mi
Registration #11	2012-10-10	91.430 mi
Registration #12	2013-09-25	92.763 mi
Registration #13	2015-04-15	92.829 mi
Registration #14		71.777 es
Registration #15		11.177 es
Registration #16		71.777 es
Registration #17		11.177 es
Registration #18		11.777 es
Registration #19		11.177 es
Registration #20		11.777 ea
Registration #21		11.777 mi
Registration #22		11.777 ea
_		
Registration #23		11.777 es
Registration #23 Registration #24		11.777 es



Car features

S0225	Air conditioning
S0295	
50482	
50501	
60566	
50567	
50569	

Safety ratings

NCAP rating	*****
Video	see crash video



Additional information

-	
Fuel tank capacity	51
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	03448620

CarCheck.co.uk page 14/14