





report date: 2024-03-29

General information

Make	PEUGEOT
Model	EXPERT L2 E7 TAXI
Colour	Black
Year of manufacture	2010
Top speed	99 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	37.7 mpg
CO2 emission	194 g/km
CO2 label	I



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Entry 1


Date 2021-11-01

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



WK60EDR report date: 2024-03-29

MOT history

MOT expiry date	2024-11-01
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	26
Total items failed	11

MOT #14		2023-11-02 08:28
MOT test nur	mber	980714539851
Result		✓ Passed
Next expiry of	date	2024-11-01
Advice No	earside Front Suspension arm pin or bush worn but not resulting in e	xcessive movement (5.3.4
Advice Of condition (1.1	offside Front Brake disc worn, pitted or scored, but not seriously weak	ened Inner surface in poor
Advice Of	ffside Front Suspension arm pin or bush worn but not resulting in exc	cessive movement (5.3.4 (a)
	arking brake efficiency only just met. It would appear that the braking r repair. Little reserve travel (1.4.2 (a) (i))	g system requires
Advice Of	ffside Rear Light unit damaged	
Advice No condition (1.1	earside Front Brake disc worn, pitted or scored, but not seriously weal.14 (a) (ii))	akened Inner surface in poor

CarCheck.co.uk page 3/14



Advice

Advice

condition (1.1.14 (a) (ii))

(a) (i))

Fail

Result

(b) (i))

WK60EDR

report date: 2024-03-29

✓ Passed

MOT #13 2023-10-25 08:14 **MOT** test number 896430766375 Result × Failed Fail Windscreen washer not working (3.5 (a)) Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) Fail Fail Offside Rear Parking brake inoperative on one side (1.4.1 (a)) **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened Inner surface in poor condition (1.1.14 (a) (ii)) Fail Offside Rear Body component damaged and likely to cause injury Light unit, sharp edges (6.2.1 (a) (i)) Offside Front Position lamp not working (4.2.1 (a) (ii)) Fail Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) Fail

ingress of dirt (6.1.7 (g) (ii))

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened Inner surface in poor

Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the

MOT #12 2022-10-27 15:52

MOT test number 958939669615

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #11 2022-10-27 10:29

MOT test number 220116247692

Result X Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10 2021-09-21 11:34

MOT test number 609445671321

Result

Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9 2020-09-21 11:00

MOT test number 110159397301

Result ✓ Passed

MOT #8 2019-09-27 11:58

MOT test number 808557229703

Advice Front brakes worn

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #7 2018-10-08 11:28

MOT test number 631350595601

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6 2017-10-02 09:49

MOT test number 188350185461

Result ✓ Passed

MOT #5 2017-10-02 09:49

MOT test number 425196320686

Result X Failed

Pass with rectification Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #4 2016-09-17 07:59

MOT test number 964911743822

Advice Offside Rear Direction indicators slightly discoloured (1.4.A.2f)

Advice Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)

MOT #3 2015-09-18 12:45

MOT test number 530606445933

Result

Passed

MOT #2 2014-09-16 09:58

MOT test number 278709354234

Result ✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #1 2013-07-15 14:45

MOT test number 256796393150

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	1 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Plate since

WK60EDR

report date: 2024-03-29

More info >

Owner history	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
HEREETE STATE OF THE STATE OF T	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	OK OK
Plate since	999-09-0
Exercised contributions	SE (

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Registration #16

Odometer	In kilometers
Mileage registrations	16
First mileage registration	2010-12-30
Last registration	2023-11-02
Complete history	See info



Registration #1	2010-12-30	9 mi
Registration #2	2013-07-15	21.206 mi
Registration #3	2014-09-16	27.478 mi
Registration #4	2015-09-18	29.333 mi
Registration #5	2016-09-17	33.484 mi
Registration #6	2017-10-02	35.821 mi
Registration #7	2017-10-02	35.821 mi
Registration #8	2018-10-08	37.215 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
S0569	

Dimensions & weight

Width	1986 mm
Height	1980 mm
Length	5135 mm
Max. allowed weight	2791 kg

Additional information

Number of seats	9
Number of axles	2
Engine number	DYXB4020048

CarCheck.co.uk page 14/14