



BV60LDJ

report date: 2024-03-28

General information

Make	FORD
Model	MONDEO ZETEC TDCI
Colour	Black
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	10.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	320 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg





Internet history

Entry 1

Date	2021-10-16
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT #11	2021-10-16 13:41
MOT test number	321305360269
Result	✓ Passed
Next expiry date	2022-10-15

MOT #10	2021-10-15 14:03
MOT test number	672262642546
Result	✗ Failed

- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #9	2020-09-14 09:53
MOT test number	611900175831
Result	✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both fronts (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive wet but not dripping (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge and cracking (5.2.3 (e))

**MOT #8** 2019-09-12 10:07**MOT test number** 780154890776**Result** ✓ Passed

- Advice** Offside Rear Coil spring corroded in arm cups (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush perishing slightly (5.3.4 (a) (i))
- Advice** Nearside Rear Coil spring corroded in arm cups (5.3.1 (b) (i))
- Advice** Nearside Rear tyre has slight moulding lump on inside side wall marked in yellow
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush perishing slightly (5.3.4 (a) (i))

MOT #7 2018-09-11 11:11**MOT test number** 414512371507**Result** ✓ Passed**MOT #6** 2018-09-11 11:11**MOT test number** 866081666461**Result** ✗ Failed

- Pass with rectification** Nearside Rear All direction indicators incorrect colour (4.4.3 (a))
- Pass with rectification** Offside Rear All direction indicators incorrect colour (4.4.3 (a))

**MOT #5** 2017-09-11 12:44**MOT test number** 549622378343**Result** ✓ Passed**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Exhaust has a minor leak of exhaust gases middle section (7.1.2)**MOT #4** 2016-09-15 14:12**MOT test number** 276391864947**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to the legal limit edge (4.1.E.1)**Advice** Offside Rear Trailing arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Rear Direction indicator slightly discoloured both rears (1.4.A.2f)**Advice** Nearside Rear Trailing arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2015-09-15 10:53**MOT test number** 347746026249**Result** ✓ Passed**MOT #2** 2014-09-15 16:25**MOT test number** 696438554211**Result** ✓ Passed



MOT #1	2013-07-13 09:28
MOT test number	577124493134
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Rear registration plate delaminated but not likely to be misread (6.3.1d)
Advice	Front registration plate delaminated but not likely to be misread (6.3.1d)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 XXXX XX
Plate since	2024-03-28
Current registration	 XXXX XX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-09-02
Last registration	2021-10-16
Complete history	See info



Registration #1	2010-09-02	20 mi
Registration #2	2013-07-13	24.987 mi
Registration #3	2014-09-15	34.339 mi
Registration #4	2015-09-15	42.468 mi
Registration #5	2016-09-15	50.693 mi
Registration #6	2017-09-11	58.862 mi
Registration #7	2018-09-11	66.172 mi
Registration #8	2019-09-11	74.482 mi
Registration #9	2020-09-11	82.832 mi
Registration #10	2021-09-11	91.232 mi
Registration #11	2022-09-11	99.682 mi
Registration #12	2023-09-11	108.182 mi
Registration #13	2024-03-28	116.732 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Kerb weight	1505 kg
Max. allowed weight	2150 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	AM40965
---------------	---------