



report date: 2024-03-29

General information

Make	NISSAN
Model	NV200 DCI ACENTA COMBI
Colour	White
Year of manufacture	2013
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	53.3 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-03-17
Pictures	3
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-12
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	12
Total items failed	17

MOT #17	2023-09-29 12:20
MOT test number	160968236829
Result	✓ Passed
Next expiry date	2024-10-12
Minor	Offside Front Obligatory mirror slightly loose (3.3 (b) (i))
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Front Items removed from driver's view prior to test Phone holder removed from windscreen.
Minor	Nearside Front Obligatory mirror slightly loose (3.3 (b) (i))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #16**

2023-09-26 14:53

**MOT test number**

501796368258

**Result****✗ Failed****Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Minor** Nearside Front Obligatory mirror slightly loose (3.3 (b) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Minor** Offside Front Obligatory mirror slightly loose (3.3 (b) (i))**Fail** Nearside Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Rear of N/S sill rusted and holed. (5.3.6 (a) (i))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Front Items removed from driver's view prior to test Phone holder removed from windscreen.**MOT #15**

2022-09-22 11:12

**MOT test number**

117930470170

**Result****✓ Passed****Minor** Offside Obligatory mirror slightly loose (3.3 (b) (i))**MOT #14**

2022-09-22 11:12

**MOT test number**

729054935415

**Result****✗ Failed****Minor** Offside Obligatory mirror slightly loose (3.3 (b) (i))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))

**MOT #13** 2021-09-29 12:24**MOT test number** 658890909473**Result** ✓ Passed**MOT #12** 2021-09-27 14:40**MOT test number** 823181635463**Result** ✗ Failed**Fail** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (ii))**MOT #11** 2020-10-13 11:06**MOT test number** 286743471976**Result** ✓ Passed**MOT #10** 2019-12-28 16:20**MOT test number** 100357362322**Result** ✓ Passed**MOT #9** 2019-09-18 10:22**MOT test number** 606094320929**Result** ✓ Passed**MOT #8** 2019-09-18 10:22**MOT test number** 640332978497**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**MOT #7** 2018-10-01 11:29**MOT test number** 496899451726**Result** ✓ Passed

**MOT #6** 2018-10-01 11:29**MOT test number** 511766916370**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Pass with rectification** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #5** 2017-09-25 15:53**MOT test number** 467759719069**Result** ✓ Passed**MOT #4** 2016-10-04 12:58**MOT test number** 407100883106**Result** ✓ Passed**MOT #3** 2016-06-09 12:11**MOT test number** 707086158327**Result** ✓ Passed**MOT #2** 2016-06-08 15:19**MOT test number** 795346210412**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)



MOT #1	2015-12-04 16:19
MOT test number	357594369755
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
12 October 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	12 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2013-10-17
Last registration	2023-09-29
Complete history	<a href="#">See info</a>



Registration #1	2013-10-17	14 mi
Registration #2	2015-12-04	24.940 mi
Registration #3	2016-06-08	40.488 mi
Registration #4	2016-06-09	40.498 mi
Registration #5	2016-10-04	50.007 mi
Registration #6	2017-09-25	74.580 mi
Registration #7	2018-10-01	84.491 mi
Registration #8	2018-10-01	84.491 mi
Registration #9	2019-09-18	99.408 mi
Registration #10	2019-09-18	99.408 mi
Registration #11	2019-09-18	99.408 mi
Registration #12	2019-09-18	99.408 mi
Registration #13	2019-09-18	99.408 mi
Registration #14	2019-09-18	99.408 mi
Registration #15	2019-09-18	99.408 mi
Registration #16	2019-09-18	99.408 mi
Registration #17	2019-09-18	99.408 mi
Registration #18	2019-09-18	99.408 mi
Registration #19	2019-09-18	99.408 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1695 mm
Height	1860 mm
Length	4400 mm
Kerb weight	1378 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	048784