




report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Green
Year of manufacture	2005
Top speed	123 mph
0 - 60 mph	9.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	331 Nm at 1.800 rpm
Engine capacity	1.988 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





YG55DYC


report date: 2024-03-28

Internet history

Entry 3

Date 2021-11-16

Pictures	24
----------	----

Listing price [View report](#)

source: cargurus.co.uk

Entry 2

Date 2021-09-20

Pictures	23
----------	----

Listing price [View report](#)



source: cargurus.co.uk

Entry 1

Date 2021-09-18

Pictures	23
----------	----

Listing price [View report](#)

source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-28
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	42
Total items failed	10

MOT #20	2023-09-26 11:42
MOT test number	467047667812
Result	✓ Passed
Next expiry date	2024-09-28
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #19	2022-09-28 10:29
MOT test number	468717356481
Result	✓ Passed
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened Both sides, corroded and pitted (1.1.14 (a) (ii))
Advice	Offside Rear Inner Integral body structure is corroded but structural rigidity is not significantly reduced Sill corroded behind skirting (6.1.1 (c) (i))
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Nearside Rear Trailing arm bush worn
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Low on tread and perished (5.2.3 (e))
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
Advice	Rear Coil spring corroded Both sides (5.3.1 (b) (i))

**MOT #18**

2022-09-24 09:09

MOT test number

327740626715

Result

✗ Failed

- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Offside Front Inner Tyre has ply or cords exposed 225/45r17 (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge Low on tread and perished (5.2.3 (e))
- Fail** Offside Front Headlamp reflector seriously defective Internals insecure (4.1.1 (b) (ii))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Rear Coil spring corroded Both sides (5.3.1 (b) (i))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge Low on tread and heavily worn on inner tread. Advise early replacement (5.2.3 (e))
- Advice** Nearside Rear Trailing arm bush worn
- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened Both sides, corroded and pitted (1.1.14 (a) (ii))
- Advice** Offside Rear Inner Integral body structure is corroded but structural rigidity is not significantly reduced Sill corroded behind skirting (6.1.1 (c) (i))

MOT #17

2021-09-29 13:49

MOT test number

417373679708

Result

✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Outer cv boot has slight leak
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #16

2020-11-06 16:16

MOT test number

437640395885

Result

✓ Passed

- Advice** O/s/f outer cv boot leaking grease

**MOT #15** 2019-10-29 17:45**MOT test number** 849266408490**Result** ✓ Passed**MOT #14** 2019-10-29 15:06**MOT test number** 844152391290**Result** ✗ Failed

Fail Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #13 2018-10-26 13:30**MOT test number** 509960587377**Result** ✓ Passed

Minor Headlamp lens slightly defective both cloudy causing weak pattern (4.1.1 (b) (i))

Minor Windscreen wiper blade defective both poor condition (3.4 (b) (i))

Minor Offside Front Anti-roll bar ball joint dust cover severely deteriorated both (5.3.4 (b) (i))

MOT #12 2017-11-01 09:57**MOT test number** 829326619235**Result** ✓ Passed

Advice Both rear tyres cracking in tread

Advice O/s/f outer cv boot has a slight leak of grease

Advice Offside Front Upper Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**MOT #11** 2016-10-18 09:07**MOT test number** 561096924842**Result** ✓ Passed**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Tyre worn on outer edge**Advice** Nearside Front Tyre worn on outer edge**MOT #10** 2015-11-02 15:33**MOT test number** 205171197155**Result** ✓ Passed**MOT #9** 2015-10-29 11:19**MOT test number** 197544434104**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar has excessive play in a pin/bush (2.4.G.2)**Fail** Offside Rear Tie bar/rod has excessive play in a pin/bush (2.4.G.2)**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)**Fail** Offside Front Anti-roll bar has excessive play in a pin/bush (2.4.G.2)**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)**MOT #8** 2014-10-21 12:10**MOT test number** 969234994263**Result** ✓ Passed**Notice** NSR brake pads low.**Advice** Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #7** 2013-10-28 16:27**MOT test number** 707671503370**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Notice** Stone chip n/s/f windscreen, both front tyres worn low & n/s/f tyre has damaged to outer side wall.**MOT #6** 2013-10-28 10:20**MOT test number** 576601803334**Result** ✗ Failed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Notice** Stone chip n/s/f windscreen, both front tyres worn low & n/s/f tyre has damaged to outer side wall.**Fail** Nearside Front Headlamp aim too far to the left (1.8)**MOT #5** 2012-10-15 09:58**MOT test number** 879179482201**Result** ✓ Passed**Notice** Undertray preventing a full mot inspection**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Near side front tyre damaged on the outer side wall**MOT #4** 2011-11-08 16:55**MOT test number** 456342211400**Result** ✓ Passed**MOT #3** 2010-10-08 16:18**MOT test number** 341121180232**Result** ✓ Passed



MOT #2	2009-08-21 11:15
MOT test number	690873839265
Result	✓ Passed

MOT #1	2008-09-17 13:01
MOT test number	822811968249
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
28 September 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	28 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	YG55DYC
Plate since	2024-03-28
Current registration	YG55DYC
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-10-31
Last registration	2023-09-26
Complete history	See info



Registration #1	2005-10-31	27 mi
Registration #2	2008-09-17	29.428 mi
Registration #3	2009-08-21	37.835 mi
Registration #4	2010-10-08	47.584 mi
Registration #5	2011-11-08	59.974 mi
Registration #6	2012-10-15	82.099 mi
Registration #7	2013-10-28	104.141 mi
Registration #8	2013-10-28	104.141 mi
Registration #9	2014-10-21	110.952 mi
Registration #10	2015-10-29	114.069 mi
Registration #11	2015-11-02	114.100 mi
Registration #12	2016-10-18	116.906 mi
Registration #13	2016-10-18	116.906 mi
Registration #14	2016-10-18	116.906 mi
Registration #15	2016-10-18	116.906 mi
Registration #16	2016-10-18	116.906 mi
Registration #17	2016-10-18	116.906 mi
Registration #18	2016-10-18	116.906 mi
Registration #19	2016-10-18	116.906 mi
Registration #20	2016-10-18	116.906 mi
Registration #21	2016-10-18	116.906 mi
Registration #22	2016-10-18	116.906 mi
Registration #23	2016-10-18	116.906 mi
Registration #24	2016-10-18	116.906 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1483 mm
Length	4716 mm
Wheel base	2710 mm
Kerb weight	1575 kg
Max. allowed weight	2075 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	0502040858226G