



PXIIYZL

report date: 2024-03-29

General information

Make	MAZDA
Model	2 TS2
Colour	Grey
Year of manufacture	-
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	122 Nm at 3.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	54.3 mpg



LABEL UNKNOWN

**MOT history**

MOT #9	2020-01-06 15:56
MOT test number	905240775304
Result	✓ Passed
Next expiry date	2021-01-24
Advice	Play in steering rack inner joint(s)
Advice	Rear Brake pipe corroded, covered in grease or other material Both (1.1.11 (c))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8	2019-01-11 16:06
MOT test number	274629473073
Result	✓ Passed
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Brake pedal wearing smooth (1.1.2 (c))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Play in steering rack inner joint(s)

**MOT #7**

2019-01-11 10:06

MOT test number

843255882027

Result**✗ Failed**

- Advice** Offside Front Play in steering rack inner joint(s)
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6

2018-01-23 10:43

MOT test number

925543308117

Result**✓ Passed**

- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

MOT #5

2018-01-23 09:46

MOT test number

481755247818

Result**✗ Failed**

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm inner edge cord exposed (4.1.E.1)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Fail** Offside Rear position lamp(s) not working (1.1.A.3b)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm inner edge cord exposed (4.1.E.1)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**MOT #4** 2017-01-25 12:17**MOT test number** 433748625268**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2015-10-27 10:21**MOT test number** 642349328023**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit worn to 3mm (4.1.E.1)**MOT #2** 2014-11-10 12:15**MOT test number** 735414214300**Result** ✓ Passed**Notice** Brake pedal soft**Notice** Steering column clonking**MOT #1** 2014-03-13 12:22**MOT test number** 118212974461**Result** ✓ Passed**Notice** Knocking noise from steering column



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2011-03-31
Last registration	2020-01-06
Complete history	See info



Registration #1	2011-03-31	11 mi
Registration #2	2014-03-13	66.923 mi
Registration #3	2014-11-10	81.805 mi
Registration #4	2015-10-27	97.457 mi
Registration #5	2017-01-25	119.574 mi
Registration #6	2018-01-25	131.277 mi
Registration #7	2018-01-25	131.277 mi
Registration #8	2018-01-25	131.277 mi
Registration #9	2018-01-25	131.277 mi
Registration #10	2020-01-06	131.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1475 mm
Length	3885 mm
Wheel base	2490 mm
Kerb weight	1025 kg
Max. allowed weight	1455 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	ZJ 915524