





report date: 2024-03-28

#### General information

Make	PEUGEOT
Model	207 ACTIVE
Colour	White
Year of manufacture	2011
Top speed	104 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	73 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	44.8 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/14



# Internet history

#### Entry 1

Date 2021-02-03

Pictures 7

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-04-27
MOT pass rate	56 %
MOT passed	9
Failed MOT tests	7
Total advice items	28
Total items failed	21

MOT #16	2024-04-27 09:07
MOT test number	387165602576
Result	🗙 Failed
Fail Nearside Rear Service brake excessively binding (1.2.1 (f))	
Advice Central Front Exhaust mounting defective (6.1.2 (a))	
Advice Nearside Rear Nail in tyre	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))	,
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (i	i))

CarCheck.co.uk page 3/14



MOT #15 2023-04-27 10:25

**MOT test number** 654560544672

**Result** ✓ Passed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Central Front Exhaust mounting defective mounting bolt loose (6.1.2 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear Nail in tyre

**MOT #14** 2023-04-17 11:47

**MOT test number** 624967873185

Result X Failed

**Advice** Nearside Rear Nail in tyre

**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Central Front Exhaust mounting defective mounting bolt loose (6.1.2 (a))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13 2022-04-25 10:21

MOT test number 799361034439

Result 

Passed

**Advice** Nearside Rear Nail in tyre

Advice Central Front Exhaust mounting defective mounting bolt loose (6.1.2 (a))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #12

MOT test number

901947472946

Result

Advice Central Front Exhaust mounting defective mounting bolt loose (6.1.2 (a))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Rear Nail in tyre

**MOT #11** 2021-04-28 14:14 **MOT** test number 314883593796 Result ✓ Passed 2021-04-28 10:15 **MOT #10 MOT** test number 196542379855 Result × Failed Fail Offside Front Headlamp aim not tested (4.1.2 (b)) Minor Nearside Front Tyre obviously under inflated (5.2.3 (I)) Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) Fail Offside Front Steering column universal joint insecure (2.1.3 (a) (i))

MOT #9	2021-02-02 16:23
MOT test number	100760246026
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/14



report date: 2024-03-28

**MOT #8** 2021-01-30 09:15 660350273419 **MOT** test number Result × Failed Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail Offside Rear Service brake excessively binding (1.2.1 (f)) Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i)) Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Fail Offside Rear Service brake effort inadequate at a wheel (1.2.1 (a) (i))

MOT test number

Result

Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6	2019-09-14 10:44
MOT test number	337352516676
Result	<b>×</b> Failed
Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (	b))
Fail Exhaust system insecure (6.1.2 (a))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)	))
Fail Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))	
Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT test number

Result

Advice Slight Free Play Steering Wheel

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #4 2017-07-17 09:55

MOT test number 148181886177

Result ✓ Passed

MOT test number

Result

Pass with rectification

Rear Exhaust system not adequately supported silencer box (7.1.1)

MOT #2

MOT test number

836883697350

Result

✓ Passed

MOT #1 2015-04-14 12:02

MOT test number 865464805181

Result ✓ Passed

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 May
Days left	2
MOT expiry date	27 April 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Venicle class	40
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



·

# Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this PEUGEOT had different number plates. ober of plates faste since More info >

CarCheck.co.uk page 11/14



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-12-10
Last registration	2024-04-27
Complete history	See info



Registration #1	2011-12-10	28 mi
Registration #2	2015-04-14	28.433 mi
Registration #3	2016-07-18	40.046 mi
Registration #4	2017-07-17	49.082 mi
Registration #5	2017-07-17	49.082 mi
Registration #6	2018-08-03	65.495 mi
Registration #7	2019-09-14	68.923 mi
Registration #8	2019-09-17	68.924 mi
Registration #9	2021-01-30	69.563 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.177 es

More info >

CarCheck.co.uk page 13/14




Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1229 kg
Max. allowed weight	1601 kg

# Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 14/14

Number of axles 2

**Engine number** FSX46458693