





report date: 2024-03-29

General information

Make	PEUGEOT	
Model	208 BLUE HDI ACCESS A/C	
Colour	White	
Year of manufacture	2016	
Top speed	106 mph	
Gearbox	5 speed Manual	

Engine & fuel consumption

Power	75 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	94.2 mpg
Consumption combined	80.7 mpg
CO2 emission	90 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history


Entry 1

Date 2021-02-03

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

2023-07-08 09:46

MOT history

MOT #6

MOT expiry date	2024-07-12
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	20
Total items failed	3

MOT #7	2023-07-13 05:42
MOT test number	750008243306
Result	✓ Passed
Next expiry date	2024-07-12

MOT te	st number 500665261243
Result	★ Failed
Fail	Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #5		2023-02-18 10:00
MOT test numbe	er	683590123098
Result		✓ Passed
Minor Nearsid	de Registration plate lamp inoperative in the case of multiple l	amps or light sources (4.7.1
Advice Offside	le Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a)	(i))

CarCheck.co.uk page 3/12



Advice

GF66XXK
report date: 2024-03-29

MOT #4 2022-02-24 13:11

1401 #4	2022-02-24 13.11
MOT test	number 919081006589
Result	✓ Passed
Advice	Offside Front Inner Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (ii))
Advice	Offside Rear tyre worn on inner edge
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)
Advice	Offside Front Tyre worn close to legal limit/worn on edge (2.8mm tread) (5.2.3 (e))
Advice	Coolant level below minimum
Advice	Front shock absorbers corroded near lower spring cups
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

Nearside Front Tyre worn close to legal limit/worn on edge (2.8mm tread) (5.2.3 (e))

CarCheck.co.uk page 4/12



(a) (i))

Advice

Advice

Advice

Coolant level below minimum

Front shock absorbers corroded near lower spring cups

GF66XXK

report date: 2024-03-29

MOT #3 2022-02-24 12:32 **MOT** test number 669141456141 Result × Failed **Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Offside Front Headlamp aim not tested (4.1.2 (b)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (2.8mm tread) (5.2.3 (e)) Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Offside Rear tyre worn on inner edge Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (2.8mm tread) (5.2.3 (e)) **Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

MOT #2

MOT test number

523768058323

Result

✓ Passed

Offside Front Inner Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (ii))

MOT #1 2019-10-28 09:43

MOT test number 620089751178

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	12 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many own have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	NK SIN
Plate since	
	Moro info

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-10-31
Last registration	2023-07-13
Complete history	See info



Registration #1	2016-10-31	6 mi
Registration #2	2019-10-28	28.514 mi
Registration #3		9.700 es
Registration #4	2021-02-25	34.640 mi
Registration #5	2022-02-24	46.523 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.117 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
50566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	88%
Children	78%
Pedestrian	61%
Safety systems	83%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1739 mm
Height	1460 mm
Length	3973 mm
Wheel base	2538 mm
Kerb weight	1075 kg
Max. allowed weight	1635 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	ge 12/12

Number of axles 2

Engine number JBHA0113588