





General information

Make	PEUGEOT
Model	107 ACCESS
Colour	White
Year of manufacture	2012
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	А







Internet history

Entry 2	
Date	2021-08-27
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date

Pictures

Listing price

20 <u>View report</u>


2021-08-26



source: autotrader.co.uk









MOT history

MOT expiry date	2024-10-19
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	21
Total items failed	4

MOT #12	2023-10-02 15:22
MOT test number	427586870007
Result	✓ Passed
Next expiry date	2024-10-19

MOT #11	2023-10-02 11:07
MOT test number	181080797032
Result	🗙 Failed
Advice Front Tyre worn close to legal limit/worn on edge o/s and n/s (5.2.3 (e))	
Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
Advice Rear Brake pipe corroded, covered in grease or other material o/s and n/s	(1.1.11 (c))

MOT #10	2022-09-26 14:00
MOT test number	102764973302
Result	✓ Passed
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

МОТ #9	2021-10-12 09:54
MOT test number	357651498833
Result	✓ Passed





МОТ #8	2020-10-20 10:41
MOT test number	343533875038
Result	✓ Passed
MOT #7	2019-10-17 09:35
MOT test number	413885873320
Result	✓ Passed

MOT #6	2019-05-15 1	6:26
MOT test	number 894956294	042
Result	V Pas	ssed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Brake pipe corroded, covered in grease or other material Both front to rears (1.1.11 (c))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5	2019-05-15 12:44
MOT test number	498827497024
Result	🗙 Failed
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Brake pipe corroded, covered in grease or other material Both front to rears (1.7)	1.11 (c))
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #4		2018-05-17 11:03
MOT test	number	791562178235
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit 2.2mm and cracking (4.1.E.1)	
Advice	Offside Front Inner Brake pad(s) wearing thin (3.5.1g)	
Advice adjustmen	Brakes imbalanced requirements only just met. It would appear that the brakir t or repair. front (3.7.B.5b)	ng system requires
Advice	Exhaust centre corroding	
Advice	Brake disc worn, pitted or scored, but not seriously weakened both front (3.5.1	.i)

MOT #3		2017-04-27 10:58
MOT test	number	344340253116
Result		✓ Passed
Advice	Front wiper slight smear	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #2	2016-05-04 11:09
MOT test number	443652798262
Result	✓ Passed
Advice Front wiper smear	
Advice Osr tyre perishing	

MOT #1		2015-05-06 13:31
MOT test	number	808866825124
Result		✓ Passed
Notice	Front wiper smearing	
Notice	Rear tyres starting to perish	



Tax & MOT check

Taxee Tax due: 1 October 2024	d	Expires: 19 October 2024	✓ МОТ
Tax status			Valid until 1 October
Days left			155
MOT expiry date			19 October 2024
Full MOT history			See MOT history
Tax calculation			
Vehicle class		48	

Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

ARMP
AMPL
F Store D
NE
ant

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and and a second s	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-05-18
Last registration	2023-10-02
Complete history	See info



Registration #1	2012-05-18	8 mi
Registration #2	2015-05-06	19.150 mi
Registration #3	2016-05-04	24.750 mi
Registration #4	2017-04-27	30.732 mi
Registration #5	2018-05-17	35.481 mi
Registration #6	2019-05-15	40.998 mi
Registration #7	2019-05-15	40.998 mi
Registration #8	2019-10-17	42.012 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 mi
Registration #13		11.777 mi
Registration #14		11.777 mi
Registration #15		11.777 mi

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings		
NCAP rating	****	0
Video	see crash video	
Dimensions & weight		
Width		1630 mm
Height		1465 mm
Length		3430 mm
Wheel base		2340 mm
Kerb weight		900 kg
Max. allowed weight		1180 kg
Additional information		
Fuel tank capacity		35 I
Fuel delivery		Multi-Point Injection
Number of doors		3
Number of seats		4
Number of axles		2
Engine number		7155098