





General information

| Make | CITROEN |
|---------------------|----------------|
| Model | DS4 HDI DSTYLE |
| Colour | White |
| Year of manufacture | 2012 |
| Top speed | 118 mph |
| 0 - 60 mph | 12.4 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 115 BHP |
|-------------------------|---------------------|
| Max. torque | 270 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 47.9 mpg |
| Consumption extra urban | 70.6 mpg |
| Consumption combined | 60.1 mpg |
| CO2 emission | 122 g/km |
| CO2 label | D |







Internet history

| Entry 1 | |
|---------------|-------------|
| Date | 2021-09-03 |
| Pictures | 38 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| MOT expiry date | 2025-01-11 |
|--------------------|------------|
| MOT pass rate | 77 % |
| MOT passed | 10 |
| Failed MOT tests | 3 |
| Total advice items | 33 |
| Total items failed | 2 |

| MOT #13 | 2024-01-12 16:52 |
|---|----------------------------|
| MOT test number | 996524017924 |
| Result | Passed |
| Next expiry date 2025-01-11 | |
| Advice Offside Front Outer Tyre has a cut but not deep enough to reach the ply (d) (i)) | / or cords 25/45x18 (5.2.3 |
| Advice Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e)) | |

| MOT #12 | | 2023-12-30 11:36 |
|--------------------------------------|---|----------------------|
| MOT test | number | 684409667325 |
| Result | | 🗙 Failed |
| Advice | Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e)) | |
| MAJOR | Offside Front Outer Drive shaft joint constant velocity boot split or insecure, | no longer prevents |
| the ingress of dirt (6.1.7 (g) (ii)) | | |
| Advice (d) (i)) | Offside Front Outer Tyre has a cut but not deep enough to reach the ply or c | ords 25/45x18 (5.2.3 |





| MOT #11 | 2022-10-27 1 | 4:08 |
|----------|--|------|
| MOT test | number 655089224 | 1935 |
| Result | V Pa | ssed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) |) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge Replace ASAP (5.2.3 (e)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i) |) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge Replace ASAP (5.2.3 (e)) | |
| Minor | Nearside Rear Rear fog lamp insecure (4.5.1 (c) (i)) | |
| Advice | Nearside Rear Outer Child Seat fitted not allowing full inspection of adult belt | |

| MOT #10 | | 2022-10-27 14:08 |
|------------|---|--------------------|
| MOT test n | number | 200752954802 |
| Result | | 🗙 Failed |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge Replace ASAP (5.2.3 (| e)) |
| Advice | Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cord | ls (5.2.3 (d) (i)) |
| Minor | Nearside Rear Rear fog lamp insecure (4.5.1 (c) (i)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Rear Outer Child Seat fitted not allowing full inspection of adult belt | |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge Replace ASAP (5.2.3 (e) |) |
| Advice | Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or core | ds (5.2.3 (d) (i)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| | n rectification Rear Registration plate lamp does not illuminate simultaneouslinps (4.7.2 (a)) | y with the |





| MOT #9 | | 2021-09-10 15:47 |
|----------|--|------------------|
| MOT test | number | 788505479605 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #8 | | 2021-07-24 09:00 |
|----------|--|------------------|
| MOT test | number | 734523057581 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #7 | 2020-08-11 10:41 |
|-----------------|------------------|
| MOT test number | 828396370398 |
| Result | ✓ Passed |

| МОТ #6 | 2019-08-16 09:51 |
|---|----------------------|
| MOT test number | 571683047915 |
| Result | ✓ Passed |
| AdviceOffside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))MinorOffside Rear Registration plate lamp inoperative in the case of multiple lam(4.7.1 (b) (i))AdviceNearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) | nps or light sources |
| Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) | |

| MOT #5 | 2018-08-20 08:11 |
|-----------------|------------------|
| MOT test number | 964162874845 |
| Result | ✓ Passed |



RUG2LHD report date: 2024-03-28

| МОТ #4 | 2017-08-21 13:45 |
|---|------------------|
| MOT test number | 836145251481 |
| Result | ✓ Passed |
| Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |

| МОТ #3 | | 2017-08-21 13:45 |
|---|---|------------------|
| MOT test number | | 762301197514 |
| Result | | 🗙 Failed |
| Advice Offside Rear Tyr | e worn close to the legal limit (4.1.E.1) | |
| Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | | |
| Pass with rectification | Nearside Registration plate lamp not working (1.1.C.1d) | |

| MOT #2 | 2016-09-17 10:48 |
|-----------------|------------------|
| MOT test number | 121135125638 |
| Result | ✓ Passed |
| | |

| MOT #1 | 2015-09-24 12:56 |
|-----------------|------------------|
| MOT test number | 301432932025 |
| Result | ✓ Passed |



Tax & MOT check

| ✓ Taxed | ✓ MOT |
|---------------------------------|-----------------------------|
| Tax due: 1 April 2025 | Expires: 11 January 2025 |
| Tax status | Valid until 1 April |
| Days left | 336 |
| MOT expiry date | 11 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | FEIDO |
| Category | Lamp |
| Туре | |
| Damage 2 | VAMPL |
| Date | ······································ |
| Category | AMP |
| Туре | |

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 6.00.000 |
|-----------------------------|----------|
| Auction value | 4 11.111 |
| Average private trade value | 4 10 200 |





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx | |
|--|-------------|
| ********** | |
| ******** | |
| ******* | |
| ************ | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this CITROEN had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | More info > |





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |



NU62LHD report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 15 |
| First mileage registration | 2012-09-27 |
| Last registration | 2024-01-12 |
| Complete history | See info |



| Registration #1 | 2012-09-27 | 11 mi |
|------------------|------------|------------|
| Registration #2 | 2015-09-24 | 32.129 mi |
| Registration #3 | 2016-09-17 | 38.184 mi |
| Registration #4 | 2017-08-21 | 44.247 mi |
| Registration #5 | 2017-08-21 | 44.247 mi |
| Registration #6 | 2018-08-20 | 50.640 mi |
| Registration #7 | 2019-08-16 | 56.957 mi |
| Registration #8 | 2020-08-11 | 62.183 mi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 esi |
| Registration #13 | | 11.777 mi |
| Registration #14 | | 11.777 mi |
| Registration #15 | | 11.777 mi |





Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 90% |
| Children | 80% |
| Pedestrian | 43% |
| Safety systems | 97% |
| Overall rating | 79% |
| Video | see crash video |



| Dimensions & weight | |
|--|--------------------------|
| Width | 1810 mm |
| Height | 1523 mm |
| Length | 4275 mm |
| Wheel base | 2612 mm |
| Kerb weight | 1320 kg |
| Max. allowed weight | 1805 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 60 I |
| | 60 l Direct Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Direct Injection |
| Fuel tank capacity Fuel delivery Number of doors | Direct Injection 5 |