



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CARAVELLE T30 SWB P/V 130TDI
Colour	Black
Year of manufacture	2009
Top speed	99 mph
0 - 60 mph	16.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.460 cc
Cylinders	5
Fuel type	Diesel
CO2 emission	219 g/km
CO2 label	K








Internet history

Entry 1

Date	2021-12-27
Pictures	17
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-05
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	34
Total items failed	8

MOT #16 2023-11-09 09:30

MOT test number 626020878876

Result ✓ Passed

Next expiry date 2024-12-05

Advice Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Rear Suspension component mounting prescribed area damaged but not considered excessive chassis member (5.3.6 (a) (i))

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #15 2022-11-19 10:42

MOT test number 395273526060

Result ✓ Passed

Advice Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))

**MOT #14** 2022-11-18 09:34**MOT test number** 453658726763**Result** ✗ Failed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Brake cable damaged but not to excess (1.1.15 (a))
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Advice** Offside Rear Brake cable damaged but not to excess (1.1.15 (a))
- Advice** Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))

MOT #13 2021-12-06 11:22**MOT test number** 625785186507**Result** ✓ Passed**MOT #12** 2020-06-18 15:46**MOT test number** 303166629271**Result** ✓ Passed

- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Centre and rear exhaust sections slightly corroded
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #11**

2020-06-18 15:46

MOT test number

394680533902

Result

✗ Failed

- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Centre and rear exhaust sections slightly corroded
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #10

2019-07-04 09:43

MOT test number

110162043912

Result

✓ Passed

- Advice** Centre and rear exhaust sections slightly corroded
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Inner Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear brake pad(s) getting low
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front brake disc(s) slightly ridged

MOT #9

2018-07-06 10:44

MOT test number

796342357444

Result

✓ Passed

MOT #8

2017-07-07 09:00

MOT test number

719520059958

Result

✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Exhaust silencers, outer skins corroded

**MOT #7**

2017-07-07 09:00

MOT test number

377700780047

Result

✗ Failed

Advice Exhaust silencers, outer skins corroded**Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6**

2016-06-28 11:29

MOT test number

562848798410

Result

✓ Passed

Advice Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Exhaust silencers outer skins corroded**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #5**

2015-07-03 11:56

MOT test number

259904585436

Result

✓ Passed

MOT #4

2015-07-02 15:13

MOT test number

419163485199

Result

✗ Failed

Fail Nearside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)



MOT #3	2014-10-30 10:20
MOT test number	246353804360
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2013-10-29 14:16
MOT test number	287772503393
Result	✓ Passed

MOT #1	2012-10-26 11:49
MOT test number	687610002343
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
5 December 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	5 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 NA59YWK
Plate since	2019-06-29
Current registration	 NA59YWK
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-10-30
Last registration	2023-11-09
Complete history	See info



Registration #1	2009-10-30	8 mi
Registration #2	2012-10-26	26.942 mi
Registration #3	2013-10-29	35.787 mi
Registration #4	2014-10-30	48.086 mi
Registration #5	2015-07-02	53.751 mi
Registration #6	2015-07-03	53.751 mi
Registration #7	2016-06-28	64.754 mi
Registration #8	2017-07-07	77.640 mi
Registration #9	2017-07-07	77.640 mi
Registration #10	2019-05-29	95.377 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi
Registration #18	2019-05-29	95.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2242 mm
Height	2170 mm
Length	4890 mm
Kerb weight	1972 kg
Max. allowed weight	3000 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	8

Engine number

BNZ 185293