





report date: 2024-03-28

General information

Make	VAUXHALL
Model	VIVARO L2H1 2900 SPORTIVE CDTI BITURBO S/S
Colour	Grey
Year of manufacture	2018

Engine & fuel consumption

Power	123 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	50.4 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/11



DY18UGS report date: 2024-03-28

Internet history


Entry 1

Date 2021-11-05

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



DY18UGS report date: 2024-03-28

MOT history

MOT expiry date	2025-02-11
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	8
Total items failed	4

MOT #6		2024-02-12 17:44
MOT test	number	479340295098
Result		✓ Passed
Next exp	iry date	2025-02-11
Minor	Offside Obligatory mirror slightly damaged (3.3 (b) (i))	
Minor	Nearside Obligatory mirror slightly damaged (3.3 (b) (i))	
Advice	Advice Offside Front Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))	
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Worn on inner ed	ge (5.2.3 (e))

MOT #5		2022-12-01 16:10
MOT test	number	935658371834
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened Bo	oth rear discs (1.1.14 (a) (ii))

MOT #4	2022-12-01 16:10
MOT test number	917281032230
Result	≍ Failed
Pass with rectification	Central Upper Stop lamp(s) not working (4.3.1 (a) (ii))
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both rear discs (1.1.14 (a) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #3 2021-11-24 14:19 **MOT test number** 863829020273 Result ✓ Passed MOT #2 2021-04-30 13:06 **MOT** test number 141790789439 Result ✓ Passed MOT #1 2021-04-30 09:15 **MOT test number** 957368858267 Result × Failed Central Rear Undertray insecure Axel cover clips broken and insecure. (8.1.1 (b) (i)) Fail Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Fail Nearside Front Headlamp aim too low (4.1.2 (a)) **Advice** Driver's view Items removed from driver's view prior to test Phone holder (3.1 (a) (ii))

CarCheck.co.uk page 4/11



DY18UGS report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	11 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category


Damage 2

Category

Type

Date

Туре



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

More info >

Owner history

e mile. mistery	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloshere.	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	NE SIE
Plate since	
Current registration	NK WE
Plate since	

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-05-22
Last registration	2024-02-12
Complete history	See info



Registration #1	2018-05-22	22 mi
Registration #2	2021-04-30	73.792 mi
Registration #3	2021-04-30	73.792 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



DY18UGS report date: 2024-03-28

Safety ratings

NCAP rating	***
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5398 mm
Kerb weight	1760 kg
Max. allowed weight	3040 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	R9M D4 - C332000LQI

CarCheck.co.uk page 11/11