






report date: 2024-03-29

General information

Make	MINI
Model	COOPER SD
Colour	Silver
Year of manufacture	2013
Top speed	130 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2021-06-28

Pictures 12

Listing price <u>View report</u>










source: cargurus.co.uk

Entry 1

Date	2021-05-26
Pictures	20
Listing price	<u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-01-25
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	8
Total items failed	6

MOT #14	2024-01-26 13:58
MOT test number	367190948874
Result	✓ Passed
Next expiry date	2025-01-25

MOT #13	2023-07-28 12:48
MOT test number	947284802860
Result	✓ Passed

MOT #12	2022-09-23 12:37
MOT test number	299964825381
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #11		2022-09-23 12:37
MOT test number		130378673873
Result		X Failed
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))	

CarCheck.co.uk page 3/12



MOT #10 2021-03-31 07:38

MOT test number 551023613329

Result ✓ Passed

MOT #9 2020-03-20 11:27

MOT test number 202229571190

Result ✓ Passed

MOT #8 2020-03-20 08:37

MOT test number 117884045183

Result X Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2019-04-05 07:56

MOT test number 119592834352

Result \rightarrow Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2019-03-30 11:38

MOT test number 953405775757

Result X Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #5 2018-04-05 14:42

MOT test number 825258777364

Result

Passed

CarCheck.co.uk page 4/12



MOT #4 2018-04-05 12:06

MOT test number 820488536310

Result × Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Rear wear to edge and light cracking

MOT #3 2017-03-23 06:39

MOT test number 619446977924

Result \(\sqrt{Passed} \)

MOT #2 2016-09-30 13:21

MOT test number 343674164624

Result \rightarrow Passed

Advice Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)

MOT #1 2016-09-30 08:37

MOT test number 235782256015

Result X Failed

Advice Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)

Fail Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

CarCheck.co.uk page 5/12



Tax & MOT check

Tax expired: 19 June 2023





Expires: 25 January 2025

Tax status	Expired at 19 June 2023
Days left	314 days too late
MOT expiry date	25 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>k</u>		e?

	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-09-23
Last registration	2024-01-26
Complete history	See info



Registration #1	2013-09-23	24 mi
Registration #2	2016-09-30	26.117 mi
Registration #3	2016-09-30	26.117 mi
Registration #4	2017-03-23	27.499 mi
Registration #5	2018-04-05	48.088 mi
Registration #6	2018-04-05	48.008 mi
Registration #7	2019-03-30	60.589 mi
Registration #8	2019-04-05	60.805 mi
Registration #9	2020-03-20	72.596 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		9.77 66
Registration #14		11.777 es
Registration #15		9.77 66
Registration #16		11.777 es
Registration #17		11.777 ms

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1913 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1150 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/1