



HYUNDAI



SMIILNW


report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Black
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 1.900 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	176 g/km
CO2 label	I





MOT history

MOT expiry date	2021-02-24
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	7
Total items failed	2

MOT #9	2020-02-25 15:14
MOT test number	631365276959
Result	✓ Passed
Next expiry date	2021-02-24

MOT #8	2019-05-29 09:47
MOT test number	673114973690
Result	✓ Passed

MOT #7	2019-05-29 09:47
MOT test number	515581294484
Result	✗ Failed
Pass with rectification	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #6	2018-06-07 13:43
MOT test number	185873089278
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2017-05-23 08:38**MOT test number** 658910666153**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #4** 2016-06-08 13:42**MOT test number** 292058455367**Result** ✓ Passed**MOT #3** 2016-05-31 10:14**MOT test number** 149802923840**Result** ✗ Failed**Fail** Nearside Front Inner Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #2** 2015-06-08 11:43**MOT test number** 288639855125**Result** ✓ Passed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #1** 2014-06-11 16:55**MOT test number** 308392864120**Result** ✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	 
Plate since	2019-09-29
Current registration	 
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2011-05-31
Last registration	2020-02-25
Complete history	See info



Registration #1	2011-05-31	26 mi
Registration #2	2014-06-11	36.047 mi
Registration #3	2015-06-08	49.955 mi
Registration #4	2016-05-31	63.579 mi
Registration #5	2016-06-08	63.940 mi
Registration #6	2016-06-08	63.940 mi
Registration #7	2016-06-08	63.940 mi
Registration #8	2016-06-08	63.940 mi
Registration #9	2016-06-08	63.940 mi
Registration #10	2016-06-08	63.940 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1760 mm
Length	4660 mm
Wheel base	2700 mm
Kerb weight	1920 kg
Max. allowed weight	2570 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

