



report date: 2024-03-28

General information

Make	FORD
Model	FUSION FUSION +
Colour	Grey
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.2 mpg
CO2 emission	181 g/km
CO2 label	I





Internet history

Entry 2

Date	2021-09-18
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-08-25
Pictures	1
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-11-26
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	29
Total items failed	4

MOT #18	2023-11-27 11:54
MOT test number	701234515321
Result	✓ Passed
Next expiry date	2024-11-26
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake disc worn, but not excessively both front discs (1.1.14 (a) (i))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Water moisture in both side repeaters

**MOT #17**

2023-11-22 12:31

MOT test number

525773729159

Result**✗ Failed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake disc worn, but not excessively both front discs (1.1.14 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Power steering hose not clipped into lower engine cover
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Water moisture in both side repeaters
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16

2022-10-12 08:06

MOT test number

214811830521

Result**✓ Passed****MOT #15**

2021-11-01 11:15

MOT test number

517341879672

Result**✓ Passed****MOT #14**

2021-01-22 16:11

MOT test number

805635907962

Result**✓ Passed**

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13** 2020-01-31 12:39**MOT test number** 803295754832**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Coolant level low**MOT #12** 2020-01-24 13:30**MOT test number** 368983934159**Result** ✗ Failed**MAJOR** Central Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Coolant level low**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #11** 2019-02-08 17:18**MOT test number** 612299775446**Result** ✓ Passed**MOT #10** 2018-02-09 12:42**MOT test number** 580051186828**Result** ✓ Passed**MOT #9** 2018-02-09 12:42**MOT test number** 657020792028**Result** ✗ Failed**Pass with rectification** Front Headlamp aim too high both (1.8)**Pass with rectification** Nearside Rear All position lamps not working (1.1.A.3b)

**MOT #8** 2017-01-27 10:36**MOT test number** 141576814368**Result** ✓ Passed**MOT #7** 2016-02-11 16:03**MOT test number** 750739167900**Result** ✓ Passed**Advice** Offside rear tyre heavily perished/cracking in tread area**MOT #6** 2016-02-11 14:48**MOT test number** 343186129601**Result** ✗ Failed**Advice** Offside rear tyre heavily perished/cracking in tread area**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #5** 2015-02-02 14:48**MOT test number** 569063835058**Result** ✓ Passed**MOT #4** 2015-02-02 12:07**MOT test number** 169503635480**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #3** 2014-01-27 11:08**MOT test number** 409777824071**Result** ✓ Passed



MOT #2	2013-01-31 09:29
MOT test number	636291433009
Result	✓ Passed
MOT #1	2012-01-05 10:53
MOT test number	487455102006
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
26 November 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	26 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	ML58VWK
Plate since	2019-03-28
Current registration	ML58VWK
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-02-03
Last registration	2023-11-27
Complete history	See info



Registration #1	2009-02-03	27 mi
Registration #2	2012-01-05	21.413 mi
Registration #3	2013-01-31	26.121 mi
Registration #4	2014-01-27	29.710 mi
Registration #5	2015-02-02	31.206 mi
Registration #6	2015-02-02	31.206 mi
Registration #7	2016-02-11	33.577 mi
Registration #8	2016-02-11	33.577 mi
Registration #9	2017-01-27	39.157 mi
Registration #10	2018-02-09	40.906 mi
Registration #11	2018-02-09	40.906 mi
Registration #12	2019-02-27	42.557 mi
Registration #13	2019-02-27	42.557 mi
Registration #14	2019-02-27	42.557 mi
Registration #15	2019-02-27	42.557 mi
Registration #16	2019-02-27	42.557 mi
Registration #17	2019-02-27	42.557 mi
Registration #18	2019-02-27	42.557 mi
Registration #19	2019-02-27	42.557 mi
Registration #20	2019-02-27	42.557 mi
Registration #21	2019-02-27	42.557 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1110 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9U37641