



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T30 LWB P/V 104TDI
Colour	White
Year of manufacture	2006
Top speed	99 mph
0 - 60 mph	18.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 2.000 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-17
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-25
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	14
Total items failed	13

MOT #22	2023-07-03 11:47
MOT test number	459558897745
Result	✓ Passed
Next expiry date	2024-07-25
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))

MOT #21	2022-07-08 09:19
MOT test number	682818323876
Result	✓ Passed

MOT #20	2021-07-26 10:32
MOT test number	996039267201
Result	✓ Passed

MOT #19	2020-07-20 14:14
MOT test number	273856471012
Result	✓ Passed
Advice	Exhaust starting to deteriorate

**MOT #18** 2020-07-20 12:12**MOT test number** 671933199763**Result** ✗ Failed**Advice** Exhaust starting to deteriorate**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**MOT #17** 2019-04-30 14:34**MOT test number** 521960384268**Result** ✓ Passed**Advice** Rear exhaust silencer corroded**MOT #16** 2019-04-24 11:23**MOT test number** 934110700672**Result** ✗ Failed**Fail** Exhaust emissions exceed manufacturer's specified limit limit 0.80 (8.2.2.2 (a))**Advice** Rear exhaust silencer corroded**Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #15** 2018-04-17 15:58**MOT test number** 837953034437**Result** ✓ Passed**Advice** Offside Rear tyre starting to perish outer edge**Advice** Exhaust starting to deteriorate**MOT #14** 2017-04-26 08:48**MOT test number** 730931150159**Result** ✓ Passed**Advice** Centre and rear exhaust boxes deteriorating

**MOT #13** 2016-04-19 09:52**MOT test number** 389540327892**Result** ✓ Passed**MOT #12** 2016-04-18 12:17**MOT test number** 880502968835**Result** ✗ Failed**Advice** Engine oil at min level**Fail** Nearside Lower Front suspension ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #11** 2015-05-07 09:03**MOT test number** 939407525154**Result** ✓ Passed**Notice** O.s.r tyre starting to perish**MOT #10** 2014-04-23 09:07**MOT test number** 218713214179**Result** ✓ Passed**MOT #9** 2013-05-10 13:32**MOT test number** 846430133194**Result** ✓ Passed**MOT #8** 2013-02-01 09:47**MOT test number** 466422133081**Result** ✓ Passed**MOT #7** 2012-02-10 09:58**MOT test number** 445821642062**Result** ✓ Passed

**MOT #6** 2011-05-13 09:39**MOT test number** 548313331197**Result** ✓ Passed**Notice** Rear brake discs corroded**MOT #5** 2010-04-28 16:50**MOT test number** 364998410125**Result** ✓ Passed**MOT #4** 2010-04-28 11:26**MOT test number** 461488810103**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp does not illuminate (3.4.1b)**Fail** Nearside Rear brake disc excessively pitted (3.5.1h)**MOT #3** 2010-04-27 12:52**MOT test number** 541207410110**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**MOT #2** 2009-08-27 12:26**MOT test number** 122759539247**Result** ✓ Passed



MOT #12009-08-27 10:35

MOT test number353499939428

Result		✗ Failed
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail	Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)	
Notice	Brake warning light on	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Fail	Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)	
Fail	Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
25 July 2024

<b>Tax status</b>	Valid until 1 August
-------------------	----------------------

<b>Days left</b>	94
------------------	----

<b>MOT expiry date</b>	25 July 2024
------------------------	--------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>RV56VDJ</b>
Plate since	2019-06-29
Current registration	 <b>RV56VDJ</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-09-01
Last registration	2023-07-03
Complete history	<a href="#">See info</a>



Registration #1	2006-09-01	23 mi
Registration #2	2009-08-27	49.203 mi
Registration #3	2009-08-27	49.203 mi
Registration #4	2010-04-27	55.656 mi
Registration #5	2010-04-28	55.666 mi
Registration #6	2010-04-28	55.656 mi
Registration #7	2011-05-13	56.873 mi
Registration #8	2012-02-10	58.082 mi
Registration #9	2013-02-01	65.458 mi
Registration #10	2013-05-10	67.135 mi
Registration #11	2014-04-23	68.948 mi
Registration #12	2015-05-07	71.402 mi
Registration #13	2016-05-20	75.277 mi
Registration #14	2016-05-20	75.277 mi
Registration #15	2016-05-20	75.277 mi
Registration #16	2016-05-20	75.277 mi
Registration #17	2016-05-20	75.277 mi
Registration #18	2016-05-20	75.277 mi
Registration #19	2016-05-20	75.277 mi
Registration #20	2016-05-20	75.277 mi
Registration #21	2016-05-20	75.277 mi
Registration #22	2016-05-20	75.277 mi
Registration #23	2016-05-20	75.277 mi
Registration #24	2016-05-20	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2175 mm
Height	1940 mm
Length	4707 mm
Kerb weight	1823 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	AXB 107537