



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 D3 SE LUX
Colour	Grey
Year of manufacture	2011
Top speed	134 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-03
Pictures	36
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-16
MOT pass rate	100 %
MOT passed	12
Failed MOT tests	0
Total advice items	10
Total items failed	0

MOT #12	2023-10-17 09:37
MOT test number	630829267348
Result	✓ Passed
Next expiry date	2024-11-16
Advice	Brake disc worn, but not excessively both front (1.1.14 (a) (i))
Advice	Tyre worn close to legal limit/worn on edge both rear (5.2.3 (e))

MOT #11	2022-11-08 09:39
MOT test number	737951227869
Result	✓ Passed
Advice	Tyre worn close to legal limit/worn on edge both rear (5.2.3 (e))
Advice	All direction indicators slightly discoloured both rear (4.4.3 (a))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #10	2021-11-17 09:57
MOT test number	438817884038
Result	✓ Passed
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))



MOT #9	2021-01-11 11:02
MOT test number	904418815237
Result	✓ Passed
MOT #8	2020-01-22 12:46
MOT test number	870772944293
Result	✓ Passed
MOT #7	2019-01-25 11:35
MOT test number	814401774987
Result	✓ Passed
MOT #6	2018-02-01 09:38
MOT test number	965794592444
Result	✓ Passed
MOT #5	2016-10-05 09:57
MOT test number	586489550550
Result	✓ Passed
MOT #4	2015-10-08 12:38
MOT test number	455699690931
Result	✓ Passed
MOT #3	2015-01-19 11:53
MOT test number	926469415051
Result	✓ Passed



MOT #2	2013-12-17 10:17
MOT test number	975431253397
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2011-04-11 15:38
MOT test number	448371101180
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
16 November 2024

Tax status		Valid until 1 November
Days left		187
MOT expiry date		16 November 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-01-06
Last registration	2023-10-17
Complete history	See info



Registration #1	2011-01-06	14 mi
Registration #2	2011-04-11	13.352 mi
Registration #3	2013-12-17	57.204 mi
Registration #4	2015-01-19	72.023 mi
Registration #5	2015-10-08	75.047 mi
Registration #6	2016-10-05	81.912 mi
Registration #7	2018-02-01	91.698 mi
Registration #8	2019-05-29	95.277 mi
Registration #9	2019-05-29	95.277 mi
Registration #10	2019-05-29	95.277 mi
Registration #11	2019-05-29	95.277 mi
Registration #12	2019-05-29	95.277 mi
Registration #13	2019-05-29	95.277 mi
Registration #14	2019-05-29	95.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2778 mm
Kerb weight	1672 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1028850