




report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 D5 SE
Colour	Silver
Year of manufacture	2004
Top speed	115 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	340 Nm at 3.000 rpm
Engine capacity	2.435 cc
Cylinders	5
Fuel type	Diesel
Consumption city	23.7 mpg
Consumption extra urban	37.7 mpg
Consumption combined	31.0 mpg
CO2 emission	242 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-10-25
MOT pass rate	71 %
MOT passed	17
Failed MOT tests	7
Total advice items	50
Total items failed	13

MOT #24	2023-10-25 15:44
MOT test number	767477832373
Result	✓ Passed
Next expiry date	2024-10-25

MOT #23	2022-10-26 13:47
MOT test number	288302974713
Result	✓ Passed
Advice	Rear Exhaust mounting defective just before rear silencer. exhaust still secure (6.1.2 (a))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #22	2022-10-22 11:31
MOT test number	162720186087
Result	✗ Failed
Advice	Rear Exhaust mounting defective just before rear silencer. exhaust still secure (6.1.2 (a))
Advice	Offside Front Play in steering rack inner joint(s)
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Front Play in steering rack inner joint(s)
Fail	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #21**

2021-09-10 16:08

MOT test number

942640824357

Result

✓ Passed

- Advice** Play in steering rack inner joint(s)
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Front Inner Brake disc worn, but not excessively sides of both discs are a lot thinner than the outer, close to being excessively worn (1.1.14 (a) (i))
- Advice** Offside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge edge worn (5.2.3 (e))

MOT #20

2021-09-09 16:07

MOT test number

756316432003

Result

✗ Failed

- Advice** Front Inner Brake disc worn, but not excessively sides of both discs are a lot thinner than the outer, close to being excessively worn (1.1.14 (a) (i))
- Advice** Offside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge edge worn (5.2.3 (e))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Play in steering rack inner joint(s)
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #19** 2020-08-26 08:19**MOT test number** 524589445316**Result** ✓ Passed

- Advice** Play in steering rack inner joint(s)
- Advice** Front Brake hose slightly deteriorated both sides (1.1.12 (b) (ii))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #18 2019-09-14 09:37**MOT test number** 617653629032**Result** ✓ Passed**MOT #17** 2019-09-14 08:48**MOT test number** 220477935599**Result** ✗ Failed

- Fail** Front Tyre tread depth below requirements of 1.6mm both (5.2.3 (e))

MOT #16 2018-08-23 12:13**MOT test number** 898081223171**Result** ✓ Passed

- Advice** Front tires close to limit

MOT #15 2018-08-23 08:56**MOT test number** 720648988860**Result** ✗ Failed

- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Position lamp not working front both sides (4.2.1 (a))
- Advice** Front tires close to limit

**MOT #14** 2017-09-07 08:55**MOT test number** 607086025415**Result** ✓ Passed**MOT #13** 2016-09-06 15:36**MOT test number** 295936379876**Result** ✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #12 2015-08-26 00:00**MOT test number** 434312142882**Result** ✓ Passed**MOT #11** 2014-08-28 17:11**MOT test number** 386770044421**Result** ✓ Passed

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #10 2014-08-27 12:50**MOT test number** 325329134419**Result** ✗ Failed

Fail Track rod end ball joint has excessive play (2.2.B.1f)

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

Fail Front position lamp(s) not working (1.1.A.3b)

Fail Parking brake: efficiency below requirements (3.7.B.7)

MOT #9 2013-09-12 12:35**MOT test number** 788505853209**Result** ✓ Passed

**MOT #8** 2013-09-12 12:35**MOT test number** 397145253292**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Front Front position lamp(s) not working (1.1.A.3b)**MOT #7** 2012-09-18 12:46**MOT test number** 898752862249**Result** ✓ Passed**MOT #6** 2011-09-30 11:24**MOT test number** 829463571230**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #5** 2010-09-22 11:35**MOT test number** 303705060213**Result** ✓ Passed**MOT #4** 2009-09-28 16:39**MOT test number** 714141379269**Result** ✓ Passed

**MOT #3**

2008-10-21 14:14

MOT test number

573405898207

Result

✓ Passed

- Notice** N/s rear subframe bush front bush
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Parking brake
- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Rear wiper blade split
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2

2008-10-17 12:53

MOT test number

994981098285

Result

✗ Failed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** N/s rear subframe bush front bush
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Notice** Parking brake
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Rear wiper blade split
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #12007-10-01 13:40

MOT test number784744177272

Result

✓ Passed

- Notice

Nail in offside rear tyre
- Advice

Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice

Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
25 October 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	25 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	KE04KWM
Plate since	2019-09-29
Current registration	KE04KWM
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-06-21
Last registration	2023-10-25
Complete history	See info



Registration #1	2004-06-21	7 mi
Registration #2	2007-10-01	28.387 mi
Registration #3	2008-10-17	38.668 mi
Registration #4	2008-10-21	38.763 mi
Registration #5	2009-09-28	46.867 mi
Registration #6	2010-09-22	53.888 mi
Registration #7	2011-09-30	64.832 mi
Registration #8	2012-09-18	75.343 mi
Registration #9	2013-09-12	86.417 mi
Registration #10	2014-08-27	99.077 mi
Registration #11	2014-08-28	99.196 mi
Registration #12	2015-08-26	108.042 mi
Registration #13	2016-09-06	117.379 mi
Registration #14	2016-09-06	117.379 mi
Registration #15	2016-09-06	117.379 mi
Registration #16	2016-09-06	117.379 mi
Registration #17	2016-09-06	117.379 mi
Registration #18	2016-09-06	117.379 mi
Registration #19	2016-09-06	117.379 mi
Registration #20	2016-09-06	117.379 mi
Registration #21	2016-09-06	117.379 mi
Registration #22	2016-09-06	117.379 mi
Registration #23	2016-09-06	117.379 mi
Registration #24	2016-09-06	117.379 mi
Registration #25	2016-09-06	117.379 mi



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1784 mm
Length	4798 mm
Wheel base	2859 mm
Kerb weight	2108 kg

Additional information

Fuel tank capacity	72 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Engine number	174233