



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Black
Year of manufacture	2010
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E









Internet history

Entry 1

Date	2022-01-26
Pictures	10
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-02-22
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	13
Total items failed	3

MOT #14 2024-02-23 11:19

MOT test number 270226892945

Result ✓ Passed

Next expiry date 2025-02-22

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened outer face pitted (1.1.14 (a) (ii))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened outer face pitted (1.1.14 (a) (ii))

MOT #13 2023-02-08 12:19

MOT test number 286120360071

Result ✓ Passed

**Minor** Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #12 2022-01-24 15:09

MOT test number 808082378033

Result ✓ Passed

**MOT #11** 2021-01-12 14:55**MOT test number** 258651247413**Result** ✓ Passed**MOT #10** 2020-01-21 14:27**MOT test number** 531694766212**Result** ✓ Passed**MOT #9** 2019-05-16 09:51**MOT test number** 481140712961**Result** ✓ Passed**MOT #8** 2019-04-16 10:38**MOT test number** 118541693219**Result** ✗ Failed**Fail** Nearside Front Suspension component pin or bush excessively worn wishbone (5.3.4 (a) (i))**Fail** Offside Front Suspension component pin or bush excessively worn wishbone (5.3.4 (a) (i))**MOT #7** 2018-07-25 13:08**MOT test number** 165491728414**Result** ✓ Passed**Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**MOT #6** 2017-07-18 10:17**MOT test number** 123747202680**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)

**MOT #5** 2016-07-22 13:24**MOT test number** 463544810883**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2015-07-20 11:13**MOT test number** 369401005413**Result** ✓ Passed**Notice** Nearside front tyre cracking in tread**MOT #3** 2015-07-20 11:13**MOT test number** 309271105448**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Notice** Nearside front tyre cracking in tread**MOT #2** 2014-07-15 12:25**MOT test number** 279206194426**Result** ✓ Passed**MOT #1** 2013-07-29 14:25**MOT test number** 747170413291**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
18 April 2024

✓

MOT

Expires:  
22 February 2025

Tax status	Expired at 18 April 2024
Days left	11 days too late
MOT expiry date	22 February 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-06-25
Last registration	2024-02-23
Complete history	<a href="#">See info</a>



Registration #1	2010-06-25	8 mi
Registration #2	2013-07-29	2.696 mi
Registration #3	2014-07-15	3.521 mi
Registration #4	2015-07-20	3.976 mi
Registration #5	2016-07-22	5.220 mi
Registration #6	2017-07-18	9.587 mi
Registration #7	2018-07-25	10.383 mi
Registration #8	2019-04-16	10.899 mi
Registration #9	2020-05-20	11.317 mi
Registration #10	2021-06-22	11.735 mi
Registration #11	2022-07-24	12.153 mi
Registration #12	2023-08-26	12.571 mi
Registration #13	2024-01-28	12.989 mi
Registration #14	2024-02-23	13.407 mi
Registration #15	2024-03-28	13.825 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CHF 058721