



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	GETZ CDX
Colour	Silver
Year of manufacture	2003
Top speed	100 mph
0 - 60 mph	11.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	81 BHP
Max. torque	116 Nm at 3.200 rpm
Engine capacity	1.341 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	45.6 mpg
Consumption combined	37.2 mpg
CO2 emission	181 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	<a href="#">View report</a>



source: autoonline.co.uk



## MOT history

MOT expiry date	2025-02-17
MOT pass rate	90 %
MOT passed	18
Failed MOT tests	2
Total advice items	13
Total items failed	3

MOT #20 2024-02-16 10:01

MOT test number 971320286123

Result ✓ Passed

Next expiry date 2025-02-17

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #19 2023-02-17 10:09

MOT test number 310852765304

Result ✓ Passed

MOT #18 2022-02-18 12:07

MOT test number 783393627200

Result ✓ Passed

**Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing slightly perishing (5.2.3 (d) (ii))

**MOT #17** 2020-12-21 12:20**MOT test number** 979091237607**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #16** 2020-12-21 12:20**MOT test number** 300685137229**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Offside Headlamp aim too far to the right (4.1.2 (a))**Pass with rectification** Rear Registration plate does not conform to the specified requirements (0.1 (d))**MOT #15** 2020-01-07 12:21**MOT test number** 636508395874**Result** ✓ Passed**MOT #14** 2019-01-04 14:29**MOT test number** 298951351740**Result** ✓ Passed**MOT #13** 2018-01-04 13:12**MOT test number** 992317927935**Result** ✓ Passed**MOT #12** 2016-12-14 15:03**MOT test number** 556094029527**Result** ✓ Passed



<b>MOT #11</b>	2016-01-06 12:36
<b>MOT test number</b>	203530712685
<b>Result</b>	✓ Passed
<b>MOT #10</b>	2015-01-06 15:40
<b>MOT test number</b>	319706605076
<b>Result</b>	✓ Passed
<b>MOT #9</b>	2014-01-08 15:18
<b>MOT test number</b>	189498604452
<b>Result</b>	✓ Passed
<b>MOT #8</b>	2014-01-08 10:10
<b>MOT test number</b>	498568104089
<b>Result</b>	✗ Failed
<b>Fail</b> Nearside Front Tyre has ply or cords exposed (4.1.D.1b)	
<b>MOT #7</b>	2013-01-08 11:03
<b>MOT test number</b>	197918903069
<b>Result</b>	✓ Passed
<b>MOT #6</b>	2012-01-09 09:36
<b>MOT test number</b>	295449402005
<b>Result</b>	✓ Passed
<b>MOT #5</b>	2011-01-05 10:40
<b>MOT test number</b>	375695301016
<b>Result</b>	✓ Passed



MOT #4	2009-12-02 14:35
MOT test number	734416639368
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
MOT #3	2008-12-05 11:53
MOT test number	640810148343
Result	✓ Passed
MOT #2	2007-12-04 10:01
MOT test number	250808937303
Result	✓ Passed
MOT #1	2006-12-08 10:21
MOT test number	563892546376
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
17 February 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	17 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2003-12-22
Last registration	2024-02-16
Complete history	<a href="#">See info</a>



Registration #1	2003-12-22	28 mi
Registration #2	2006-12-08	5.521 mi
Registration #3	2007-12-04	6.747 mi
Registration #4	2008-12-05	7.985 mi
Registration #5	2009-12-02	9.578 mi
Registration #6	2011-01-05	11.328 mi
Registration #7	2012-01-09	12.586 mi
Registration #8	2013-01-08	13.123 mi
Registration #9	2014-01-08	13.831 mi
Registration #10	2014-01-08	13.831 mi
Registration #11	2015-01-06	14.393 mi
Registration #12	2015-01-06	14.393 mi
Registration #13	2015-01-06	14.393 mi
Registration #14	2015-01-06	14.393 mi
Registration #15	2015-01-06	14.393 mi
Registration #16	2015-01-06	14.393 mi
Registration #17	2015-01-06	14.393 mi
Registration #18	2015-01-06	14.393 mi
Registration #19	2015-01-06	14.393 mi
Registration #20	2015-01-06	14.393 mi
Registration #21	2015-01-06	14.393 mi
Registration #22	2015-01-06	14.393 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	1125 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	G4EA2272321