



Mercedes-Benz

**YK08WBF**

report date: 2024-03-29

General information

Make	MERCEDES
Model	VITO 111 CDI COMPACT P/V
Colour	White
Year of manufacture	2008
Gearbox	6 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	9999 Nm at 9.999 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-23
Pictures	6
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)



## MOT history

MOT expiry date	2024-11-03
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	62
Total items failed	18

## MOT #19 2023-10-13 09:43

MOT test number 361974141824

Result ✓ Passed

Next expiry date 2024-11-03

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Play in steering rack inner joint(s)**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Play in steering rack inner joint(s)

## MOT #18 2022-11-04 18:03

MOT test number 613086780982

Result ✓ Passed**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Brake pipe corroded, covered in grease or other material All (1.1.11 (c))**Advice** Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))**Advice** Rear Coil spring corroded both side (5.3.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))

**MOT #17**

2022-10-15 11:07

**MOT test number**

158373552250

**Result****✗ Failed**

- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Coil spring corroded both side (5.3.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Brake pipe corroded, covered in grease or other material All (1.1.11 (c))

**MOT #16**

2021-04-13 15:59

**MOT test number**

862018194834

**Result****✓ Passed**

- Advice** Reverse lights inop
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Rear diff unit mounting bushes deteriorated
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15**

2021-03-02 15:55

**MOT test number**

562810936763

**Result**

✗ Failed

**Fail** Offside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced outrigger/suspension spring saddle corrosion (6.1.1 (c) (i))

**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**Fail** Offside Steering rack has excessive free play detected at the steering wheel (steering rack fitted) rack (2.3 (a) (i))

**Fail** Nearside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced outrigger/ jacking point excessive corrosion (6.1.1 (c) (i))

**Fail** Offside Rear Brake drum back plate insecure (1.1.14 (d))

**Advice** Reverse lights inop

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords tyre in tread area (5.2.3 (d) (i))

**Fail** Front Prop shaft likely to become detached prop U-J worn to excess (6.1.7 (a) (ii))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Fail** Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #14**

2020-02-27 16:54

**MOT test number**

789474240131

**Result**

✓ Passed

**Advice** Rear slight corroded under body

**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))

**Advice** Brake pipe corroded, covered in grease or other material ALL (1.1.11 (c))

**Minor** Nearside Front Outer Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))

**MOT #13**

2020-02-27 11:33

**MOT test number**

287717132446

**Result****✗ Failed****Minor**

Nearside Front Outer Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Fail**

Front Brakes imbalanced across an axle by more than 50% (1.2.1 (b) (ii))

**Advice**

Rear Coil spring corroded both (5.3.1 (b) (i))

**Advice**

Rear slight corroded under body

**Advice**

Brake pipe corroded, covered in grease or other material ALL (1.1.11 (c))

**Advice**

Oil leak, but not excessive engine (8.4.1 (a) (i))

**MOT #12**

2019-03-05 17:18

**MOT test number**

527292645677

**Result****✓ Passed****Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**Advice**

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice**

Steering rack has slight free play detected at steering wheel (2.3 (a) (i))

**Advice**

Rear Coil spring corroded BOTH (5.3.1 (b) (i))

**Advice**

Engine management light on

**MOT #11**

2019-02-28 15:01

**MOT test number**

786121501126

**Result****✗ Failed****Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**Advice** Rear Coil spring corroded BOTH (5.3.1 (b) (i))**Fail** Headlamp not working on dipped beam BOTH (4.1.1 (a) (ii))**Advice** Engine management light on**Fail** Rear Brake disc significantly and obviously worn BOTH (1.1.14 (a) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #10**

2018-02-26 16:35

**MOT test number**

702574907238

**Result****✓ Passed****Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened and offside rear (3.5.1i)**MOT #9**

2017-03-08 16:33

**MOT test number**

828683982963

**Result****✓ Passed****Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

**MOT #8**

2017-03-02 12:17

**MOT test number**

104353262707

**Result****✗ Failed****Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Fail** Central Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Offside Steering system has excessive free play detected at the steering wheel (steering rack fitted) rack end inner joint (2.2.A.1b)**MOT #7**

2016-02-25 10:03

**MOT test number**

802725068150

**Result****✓ Passed****Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Objects removed from drivers view prior to test**Advice** Offside Rear Tyre worn close to the legal limit very close to limit (4.1.E.1)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside play in inner rack joint**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



**MOT #6** 2016-02-25 10:03**MOT test number** 106227505826**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Advice** Objects removed from drivers view prior to test**Advice** Offside Rear Tyre worn close to the legal limit very close to limit (4.1.E.1)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside play in inner rack joint**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #5** 2015-02-27 12:59**MOT test number** 659278055038**Result** ✓ Passed**MOT #4** 2014-02-26 11:51**MOT test number** 637237754019**Result** ✓ Passed**MOT #3** 2013-03-05 09:22**MOT test number** 777524363046**Result** ✓ Passed



MOT #2	2012-03-06 12:01
MOT test number	637356062055
Result	✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2011-02-23 13:57
MOT test number	935394151060
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
3 November 2024

<b>Tax status</b>	Valid until 1 January
-------------------	-----------------------

<b>Days left</b>	246
------------------	-----

<b>MOT expiry date</b>	3 November 2024
------------------------	-----------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 YK08WBF
Plate since	2024-03-29
Current registration	 YK08WBF
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-03-07
Last registration	2023-10-13
Complete history	<a href="#">See info</a>



Registration #1	2008-03-07	10 mi
Registration #2	2011-02-23	24.707 mi
Registration #3	2012-03-06	34.048 mi
Registration #4	2013-03-05	42.599 mi
Registration #5	2014-02-26	51.300 mi
Registration #6	2015-02-27	62.857 mi
Registration #7	2016-02-25	74.676 mi
Registration #8	2016-02-25	74.676 mi
Registration #9	2017-03-02	91.336 mi
Registration #10	2017-03-08	91.862 mi
Registration #11	2018-02-26	106.890 mi
Registration #12	2019-03-02	121.927 mi
Registration #13	2019-03-02	121.927 mi
Registration #14	2019-03-02	121.927 mi
Registration #15	2019-03-02	121.927 mi
Registration #16	2019-03-02	121.927 mi
Registration #17	2019-03-02	121.927 mi
Registration #18	2019-03-02	121.927 mi
Registration #19	2019-03-02	121.927 mi
Registration #20	2019-03-02	121.927 mi
Registration #21	2019-03-02	121.927 mi

More info >





Safety ratings

NCAP rating

★★★★☆

Video

[see crash video](#)



Dimensions & weight

Width	1906 mm
Height	1902 mm
Length	4748 mm
Kerb weight	1885 kg
Max. allowed weight	2770 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	64698051605488