



report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA CLUB
Colour	Green
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-06-07
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-06
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	46
Total items failed	8

MOT #16	2023-09-06 10:49
MOT test number	344702482705
Result	✓ Passed
Next expiry date	2024-09-06
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #15	2022-09-07 15:07
MOT test number	318152745983
Result	✓ Passed
Advice	Rear Brake pipe corroded, covered in grease or other material all rears (1.1.11 (c))

**MOT #14**

2021-11-25 16:13

MOT test number

789126146275

Result

✓ Passed

Minor

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Exhaust system corroding.

Advice

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #13

2020-12-14 13:55

MOT test number

479614109078

Result

✓ Passed

Advice

Offside Rear brake lens damaged

Advice

Exhaust corroding

Advice

Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Minor

Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front steering arm has slight movement at fixings

Advice

Wet test carried out

Advice

Rear Brake hose has slight corrosion to ferrule both sides (1.1.12 (f) (i))

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2020-12-11 12:23

MOT test number

188521110335

Result

✗ Failed

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front steering arm has slight movement at fixings
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Wet test carried out
- Advice** Rear Brake hose has slight corrosion to ferrule both sides (1.1.12 (f) (i))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear brake lens damaged
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust corroding

MOT #11

2019-11-28 12:20

MOT test number

339228868304

Result

✓ Passed

- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Centre stop damage to lens
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Rear Brake hose has slight corrosion to ferrule both sides (1.1.12 (f) (i))

**MOT #10** 2019-11-28 12:20**MOT test number** 912064576378**Result** ✗ Failed**Advice** Rear Brake hose has slight corrosion to ferrule both sides (1.1.12 (f) (i))**Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Centre stop damage to lens**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #9** 2018-11-19 11:46**MOT test number** 581712905909**Result** ✓ Passed**MOT #8** 2017-11-28 13:28**MOT test number** 439245882317**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit CRACKING SLIGHTLY (4.1.E.1)**Advice** Offside Rear TYRE CRACKING SLIGHTLY

**MOT #7** 2017-11-20 12:02**MOT test number** 964235657331**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Central Stop lamp emits other than a steady red light (1.2.1e)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Nearside Rear Tyre worn close to the legal limit CRACKING SLIGHTLY (4.1.E.1)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Offside Rear TYRE CRACKING SLIGHTLY**MOT #6** 2016-11-22 14:57**MOT test number** 108378886720**Result** ✓ Passed**MOT #5** 2016-11-14 12:25**MOT test number** 404278549607**Result** ✗ Failed**Fail** Offside Rear rear brake binding (3.7.B.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2015-11-17 14:32**MOT test number** 145457450140**Result** ✓ Passed



MOT #3	2014-11-26 14:35
MOT test number	609350534319
Result	✓ Passed
MOT #2	2013-11-13 10:32
MOT test number	409687313476
Result	✓ Passed
MOT #1	2012-11-30 12:34
MOT test number	146635932348
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
6 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	6 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	LV59XBJ
Plate since	2019-06-29
Current registration	LV59XBJ
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-12-11
Last registration	2023-09-06
Complete history	See info



Registration #1	2009-12-11	29 mi
Registration #2	2012-11-30	27.432 mi
Registration #3	2013-11-13	35.328 mi
Registration #4	2014-11-26	41.695 mi
Registration #5	2015-11-17	46.787 mi
Registration #6	2016-11-14	53.680 mi
Registration #7	2016-11-22	53.870 mi
Registration #8	2017-11-20	61.022 mi
Registration #9	2017-11-28	61.293 mi
Registration #10	2018-11-20	61.293 mi
Registration #11	2018-11-20	61.293 mi
Registration #12	2018-11-20	61.293 mi
Registration #13	2018-11-20	61.293 mi
Registration #14	2018-11-20	61.293 mi
Registration #15	2018-11-20	61.293 mi
Registration #16	2018-11-20	61.293 mi
Registration #17	2018-11-20	61.293 mi
Registration #18	2018-11-20	61.293 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	990 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1153344