



report date: 2024-03-29

General information

Make	NISSAN
Model	NOTE ACENTA PREMIUM DCI
Colour	Red
Year of manufacture	2016
Top speed	111 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	200 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	88.3 mpg
Consumption combined	78.5 mpg
CO2 emission	93 g/km
CO2 label	A







Internet history

Entry 1

Date	2021-09-13
Pictures	64
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-25
MOT pass rate	55 %
MOT passed	6
Failed MOT tests	5
Total advice items	29
Total items failed	6

MOT #112023-10-19 16:34

MOT test number418839089291

Result✓ Passed

Next expiry date2024-10-25

- AdviceOffside Rear Coil spring corroded (5.3.1 (b) (i))
- AdviceOffside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceNearside Rear Coil spring corroded (5.3.1 (b) (i))
- AdviceOffside Rear Nail in tyre
- AdviceOffside Front Coil spring corroded (5.3.1 (b) (i))
- AdviceOffside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10**

2023-10-19 10:48

**MOT test number**

205226305005

**Result****✗ Failed**

- Advice** Offside Rear Nail in tyre
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #9**

2022-10-20 11:34

**MOT test number**

404629538131

**Result****✓ Passed**

- Advice** Offside Front Tyre slightly damaged/cracking or perishing on sidewall (5.2.3 (d) (ii))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #8**

2022-10-20 11:34

**MOT test number**

967083749902

**Result****✗ Failed**

- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing on sidewall (5.2.3 (d) (ii))
- Pass with rectification** Offside Rear Position lamp not working (4.2.1 (a) (ii))
- Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))

**MOT #7** 2021-10-26 12:58**MOT test number** 968714410660**Result** ✓ Passed**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2021-10-26 11:14**MOT test number** 484428074052**Result** ✗ Failed**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #5** 2021-06-07 11:20**MOT test number** 547778625216**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #4** 2021-06-07 08:57**MOT test number** 309967763484**Result** ✗ Failed**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Front Bush (5.3.4 (a) (i))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Front Bush (5.3.4 (a) (i))

**MOT #3** 2020-06-12 15:27**MOT test number** 917474227803**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge Both front tyres worn on edge (5.2.3 (e))**MOT #2** 2020-06-12 14:25**MOT test number** 669288863297**Result** ✗ Failed**Advice** Tyre worn close to legal limit/worn on edge Both front tyres worn on edge (5.2.3 (e))**Fail** Front Brake disc significantly and obviously worn both (1.1.14 (a) (i))**MOT #1** 2019-05-18 09:08**MOT test number** 391199294920**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 October 2024

✓  
**MOT**

**Expires:**  
25 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	25 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2016-06-10
Last registration	2023-10-19
Complete history	<a href="#">See info</a>



Registration #1	2016-06-10	27 mi
Registration #2	2019-05-18	50.221 mi
Registration #3	2020-06-12	74.530 mi
Registration #4	2020-06-12	74.530 mi
Registration #5	2021-06-07	81.838 mi
Registration #6	2021-06-07	81.838 mi
Registration #7	2023-10-19	81.838 mi
Registration #8	2023-10-19	81.838 mi
Registration #9	2023-10-19	81.838 mi
Registration #10	2023-10-19	81.838 mi
Registration #11	2023-10-19	81.838 mi
Registration #12	2023-10-19	81.838 mi
Registration #13	2023-10-19	81.838 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	86%
Children	82%
Pedestrian	58%
Safety systems	70%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1695 mm
Height	1530 mm
Length	4100 mm
Wheel base	2600 mm
Kerb weight	1132 kg
Max. allowed weight	1615 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D035284