



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 D DRIVE SE
Colour	Silver
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	6.6 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-10-09
Pictures	21
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-14
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	9
Total items failed	2

MOT #11	2023-09-28 12:55
MOT test number	988558283642
Result	✓ Passed
Next expiry date	2024-10-14

MOT #10	2022-09-29 16:01
MOT test number	638744929284
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9	2022-09-29 11:06
MOT test number	469943004991
Result	✗ Failed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Offside Rear Service brake excessively fluctuating (1.2.1 (e))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8** 2021-10-15 08:20**MOT test number** 947801659410**Result** ✓ Passed**MOT #7** 2021-03-17 08:13**MOT test number** 188396717640**Result** ✓ Passed**MOT #6** 2020-03-12 15:55**MOT test number** 572971608722**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively BOTH FRONT DISCS N/S O/S (1.1.14 (a) (i))**MOT #5** 2019-03-06 10:05**MOT test number** 739855026889**Result** ✓ Passed**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened BOTH FRONT DISC'S (1.1.14 (a) (ii))**MOT #4** 2018-03-10 10:07**MOT test number** 433314665829**Result** ✓ Passed**MOT #3** 2017-03-17 10:17**MOT test number** 470130533572**Result** ✓ Passed**Advice** Nearside Mirror damaged**MOT #2** 2016-04-21 12:29**MOT test number** 774189986483**Result** ✓ Passed



MOT #1	2016-04-21 12:29
MOT test number	206829046414
Result	✗ Failed
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓
Taxed

Tax due:
1 October 2024

✓
MOT

Expires:
14 October 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	14 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	SM12ZGA
Plate since	2019-09-28
Current registration	SM12ZGA
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-06-29
Last registration	2023-09-28
Complete history	See info



Registration #1	2012-06-29	21 mi
Registration #2	2016-04-21	5.339 mi
Registration #3	2016-04-21	5.339 mi
Registration #4	2017-03-17	14.997 mi
Registration #5	2018-03-10	23.853 mi
Registration #6	2019-03-06	29.240 mi
Registration #7	2020-03-12	33.508 mi
Registration #8	2020-03-12	33.508 mi
Registration #9	2020-03-12	33.508 mi
Registration #10	2020-03-12	33.508 mi
Registration #11	2020-03-12	33.508 mi
Registration #12	2020-03-12	33.508 mi
Registration #13	2020-03-12	33.508 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1433 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2041867