



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS SPORT TDI DSG
Colour	Black
Year of manufacture	2007
Top speed	126 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.8 mpg
CO2 emission	177 g/km
CO2 label	I





MOT history

MOT expiry date	2021-06-22
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	39
Total items failed	8

MOT #15	2020-06-23 15:14
MOT test number	226841860553
Result	✓ Passed
Next expiry date	2021-06-22
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #14**

2020-05-28 14:35

MOT test number

645768199331

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Nearside Rear Nail in tyre
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- MAJOR** Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Emissions not tested (8.2.2.2 (e))

MOT #13

2019-06-04 13:46

MOT test number

929612898479

Result**✓ Passed**

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #12** 2019-06-04 09:30**MOT test number** 996516321141**Result** ✗ Failed

- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11 2018-05-25 09:35**MOT test number** 979585113486**Result** ✓ Passed

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10 2017-05-27 08:55**MOT test number** 578198679442**Result** ✓ Passed

**MOT #9** 2017-05-26 09:03**MOT test number** 881440532399**Result** ✗ Failed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Advice** ADVISE FRONT TYRE'S WORN RIGHT DOWN ON INSIDE , POS. TRACKING OUT**Fail** Nearside Front Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #8** 2016-06-09 15:28**MOT test number** 140026014824**Result** ✓ Passed**MOT #7** 2016-06-08 13:12**MOT test number** 836975660253**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #6** 2015-03-16 10:12**MOT test number** 167315975453**Result** ✓ Passed

**MOT #5** 2014-03-17 09:39**MOT test number** 765616174063**Result** ✓ Passed**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Notice** Under-trays fitted obscuring some underside components**Notice** Items removed from driver's view prior to test**MOT #4** 2014-03-17 09:39**MOT test number** 148186774037**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Notice** Under-trays fitted obscuring some underside components**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Notice** Items removed from driver's view prior to test**MOT #3** 2013-03-14 16:54**MOT test number** 806543273013**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2012-03-20 10:57**MOT test number** 178000982416**Result** ✓ Passed**MOT #1** 2011-03-25 15:58**MOT test number** 385224481007**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
22 January 2021

X

MOT

Expired:
22 June 2021

Tax status	Expired at 22 January 2021
Days left	1192 days too late
MOT expiry date	22 June 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 AR07KAU
Plate since	2024-03-28
Current registration	 AR07KAU
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2007-07-12
Last registration	2020-06-23
Complete history	See info



Registration #1	2007-07-12	19 mi
Registration #2	2011-03-25	40.409 mi
Registration #3	2012-03-20	46.231 mi
Registration #4	2013-03-14	52.154 mi
Registration #5	2014-03-17	58.431 mi
Registration #6	2015-03-16	63.920 mi
Registration #7	2016-06-08	68.459 mi
Registration #8	2016-06-09	68.470 mi
Registration #9	2016-06-09	68.470 mi
Registration #10	2016-06-09	68.470 mi
Registration #11	2016-06-09	68.470 mi
Registration #12	2016-06-09	68.470 mi
Registration #13	2016-06-09	68.470 mi
Registration #14	2016-06-09	68.470 mi
Registration #15	2016-06-09	68.470 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1574 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	BMM 113408