



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF GT TDI
Colour	Black
Year of manufacture	2009
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D





MOT history

MOT expiry date	2023-04-11
MOT pass rate	100 %
MOT passed	9
Failed MOT tests	0
Total advice items	16
Total items failed	0

MOT #9 2022-04-12 16:38

MOT test number 930936389833

Result ✓ Passed

Next expiry date 2023-04-11

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Anti-roll bar damaged but not seriously weakened lose (5.3.3 (b) (i))
- Advice** Nearside Non obligatory mirror damaged
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))

MOT #8 2020-07-18 11:49

MOT test number 123515065530

Result ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Inner Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #7** 2018-12-08 11:59**MOT test number** 764811987096**Result** ✓ Passed**Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Gearbox mounting defective**Advice** Parking brake lever worn, but not excessively (1.1.6 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**MOT #6** 2017-12-11 17:59**MOT test number** 838924100007**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #5** 2016-08-18 16:14**MOT test number** 532157643886**Result** ✓ Passed**MOT #4** 2015-08-17 13:46**MOT test number** 737798324033**Result** ✓ Passed**MOT #3** 2014-08-14 15:22**MOT test number** 317506924267**Result** ✓ Passed



MOT #2	2013-04-12 15:42
MOT test number	625992703104
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2012-03-14 13:34
MOT test number	696924472096
Result	✓ Passed
Notice	Covers under vehicle
Advice	Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 YD09UZU
Plate since	2019-03-28
Current registration	 YD09UZU
Plate since	2019-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2009-03-02
Last registration	2022-04-12
Complete history	See info



Registration #1	2009-03-02	12 mi
Registration #2	2012-03-14	43.721 mi
Registration #3	2013-04-12	54.600 mi
Registration #4	2014-08-14	63.207 mi
Registration #5	2015-08-17	70.308 mi
Registration #6	2016-08-17	75.377 mi
Registration #7	2017-08-17	80.446 mi
Registration #8	2018-08-17	85.515 mi
Registration #9	2019-08-17	90.584 mi
Registration #10	2022-04-12	95.653 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1299 kg
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CBA 494126