



BVI3RLX


report date: 2024-03-28

General information

Make	CITROEN
Model	DS4 HDI DSTYLE
Colour	White
Year of manufacture	2013
Top speed	118 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	122 g/km
CO2 label	D





Internet history

Entry 2

Date	2023-06-28
Pictures	0
Listing price	View report

source: [carcraft.co.uk](#)

Entry 1

Date	2021-06-03
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT expiry date	2024-06-19
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	29
Total items failed	12

MOT #15 2023-06-20 14:24**MOT test number** 950679481133**Result** Passed**Next expiry date** 2024-06-19

- Advice** Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14 2023-06-01 14:33**MOT test number** 855556259680**Result** Passed

- Advice** Nearside Rear Nail in tyre
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2023-06-01 09:52

MOT test number

305791669297

Result**✗ Failed****Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Nearside Rear Nail in tyre**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #12**

2022-05-31 09:50

MOT test number

243988246945

Result**✓ Passed****Advice** Offside Rear Nail in tyre**MOT #11**

2022-05-31 09:50

MOT test number

537810139915

Result**✗ Failed****Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**Advice** Offside Rear Nail in tyre**Pass with rectification** Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**MOT #10**

2021-06-02 10:36

MOT test number

163260612111

Result**✓ Passed**

**MOT #9** 2021-06-02 10:36**MOT test number** 333149463622**Result** ✗ Failed

- Pass with rectification** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #8 2021-01-06 15:25**MOT test number** 611194580683**Result** ✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing Outer sidewall has slight damage (5.2.3 (d) (ii))
- Advice** Nearside Rear Nail in tyre
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm & Outer sidewall has slight damage (5.2.3 (e))
- Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))

MOT #7 2019-06-28 14:49**MOT test number** 930666612957**Result** ✓ Passed

- Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))

**MOT #6** 2019-06-28 14:00**MOT test number** 492213603514**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))**MOT #5** 2018-07-05 11:51**MOT test number** 272661355210**Result** ✓ Passed**Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**MOT #4** 2017-07-12 16:36**MOT test number** 618291385481**Result** ✓ Passed**MOT #3** 2016-12-01 14:24**MOT test number** 733127932779**Result** ✓ Passed**MOT #2** 2016-12-01 14:24**MOT test number** 181305773542**Result** ✗ Failed**Pass with rectification** Front position lamp(s) not working (1.1.A.3b)



MOT #1	2016-02-22 15:47
MOT test number	225359303383
Result	✓ Passed
Advice	Offside Rear nail in tyre
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
19 June 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	19 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 BV13RLX
Plate since	2019-03-28
Current registration	 BV13RLX
Plate since	2019-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2013-03-17
Last registration	2023-06-20
Complete history	See info



Registration #1	2013-03-17	11 mi
Registration #2	2016-02-22	22.550 mi
Registration #3	2016-12-01	27.938 mi
Registration #4	2016-12-01	27.938 mi
Registration #5	2017-07-12	32.870 mi
Registration #6	2018-07-05	41.161 mi
Registration #7	2019-06-28	48.799 mi
Registration #8	2019-06-28	48.799 mi
Registration #9	2021-01-06	60.239 mi
Registration #10	2023-06-20	60.239 mi
Registration #11	2023-06-20	60.239 mi
Registration #12	2023-06-20	60.239 mi
Registration #13	2023-06-20	60.239 mi
Registration #14	2023-06-20	60.239 mi
Registration #15	2023-06-20	60.239 mi
Registration #16	2023-06-20	60.239 mi
Registration #17	2023-06-20	60.239 mi
Registration #18	2023-06-20	60.239 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	80%
Pedestrian	43%
Safety systems	97%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1523 mm
Length	4275 mm
Wheel base	2612 mm
Kerb weight	1320 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBET3041590