





report date: 2024-03-29

General information

Make	FIAT
Model	500L POP STAR
Colour	Red
Year of manufacture	2015
Top speed	111 mph
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	127 Nm at 4.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg
CO2 emission	143 g/km
CO2 label	F



CarCheck.co.uk page 1/13



Internet history

_	_	_		_	-
드	n	C	ľν	7	1

Lifety 1	
Date	2022-02-27
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT HISTORY	Μ	OT	history
-------------	---	----	---------

MOT expiry date	2024-08-02
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	12
Total items failed	14

MOT #10	2023-07-13 09:22
MOT test number	419085831481
Result	✓ Passed
Next expiry date	2024-08-02

MOT #9	2022-08-03 14:13
MOT test number	509547541466
Result	✓ Passed

MOT #8	2022-03-09 13:10
MOT test number	789525894229
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

CarCheck.co.uk page 3/13



MOT #7 2022-03-07 13:47

MOT test number 753873451238

Result X Failed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Front Exhaust has a major leak of exhaust gases (6.1.2 (a))

MOT #6 2021-08-31 15:48

MOT test number 507710279073

MOT #5 2021-08-31 15:48

MOT test number 456440075986

Result X Failed

Pass with rectification Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #4 2020-08-22 08:47

MOT test number 548086869345

Advice Child Seat fitted not allowing full inspection of adult belt 2

CarCheck.co.uk page 4/13



YT65HZE

report date: 2024-03-29

MOT test number

Result

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2019-08-30 15:05 **MOT** test number 726785395323 Result **X** Failed Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i)) Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Fail Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h)) Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail

CarCheck.co.uk page 5/13



YT65HZE

report date: 2024-03-29

MOT test number

138020240039

Result

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	2 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-


CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner	hictor.
UMMIAI	nisiaiv

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	ZIS UK
Plate since	
Current registration	UK NA
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-09-01
Last registration	2023-07-13
Complete history	See info



Registration #1	2015-09-01	28 mi
Registration #2	2018-08-21	20.186 mi
Registration #3	2019-08-30	28.129 mi
Registration #4	2019-09-02	28.129 mi
Registration #5	2020-08-22	36.309 mi
Registration #6	2021-08-31	46.795 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		71.777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	94%
Children	78%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2018 mm
Height	1667 mm
Length	4147 mm
Wheel base	2612 mm
Kerb weight	1245 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	50	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	2 13/13

Number of axles 2
Engine number 4040090