





### General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI KOMBI
Colour	Black
Year of manufacture	2018
Top speed	107 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	110 kW / 150 HP / 101 BHP
Max. torque	250 Nm at 1.300 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D








# Internet history

Entry 3	
Date	2021-06-09
Pictures	27
Listing price	View report




source: autotrader.co.uk

Entry 2	
Date	2021-06-09
Pictures	32
Listing price	View report



source: autotrader.co.uk

Entry 1	
Date	2021-06-09
Pictures	32
Listing price	View report



source: autotrader.co.uk



# MOT history

MOT expiry date	2025-04-05	
MOT pass rate	80 %	
MOT passed	4	
Failed MOT tests	1	
Total advice items	11	
Total items failed	2	

MOT #5	2024-04-05 11:29
MOT test number	498269975188
Result	✓ Passed
Next expiry date	2025-04-05

MOT #4	2023-0	3-20 11:42
MOT test	<b>number</b> 721	550003621
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #3	2022-04-04 10:33
MOT test number	402740234248
Result	✓ Passed



P	Ε	1	8	V	V	C	V
	repo	ort	dat	e:	202	24-0	3-29

MOT #2		2021-04-06 14:47
MOT test	number	794486736462
Result		✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakene	ed (1.1.14 (a) (ii))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))

MOT #1	2021-04-06 14:47
MOT test number	263241205047
Result	× Failed
Advice Nearside Rear B	rake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice Nearside Rear B	Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Pass with rectification</b> (b) (ii))	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4
Advice Offside Rear Bra	ake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Pass with rectification</b> (b) (ii))	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4
Advice Offside Rear Bra	ake pad(s) wearing thin (1.1.13 (a) (ii))



Tax & MOT check

√ Taxed	√ МОТ
Tax due: 1 November 2024	Expires: 5 April 2025
Tax status	Valid until 1 November
Days left	187
MOT expiry date	5 April 2025
Full MOT history	See MOT history

# Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FETTOR
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Date	OLE .
Category	AM
Туре	

#### Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

********	
**********	
ANALY AND A ANALY	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate sites	





#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-03-28
Last registration	2024-04-05
Complete history	See info



Registration #1	2018-03-28	26 mi
Registration #2	2021-04-06	68.137 mi
Registration #3	2021-04-06	68.137 mi
Registration #4		11.777 esi
Registration #5		11.777 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 esi

More info >





# Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
\$0566	
\$0567	
S0569	

# Safety ratings

NCAP rating	
Adult	84%
Children	78%
Pedestrian	58%
Safety systems	68%
Overall rating	74%
Video	see crash video



Dimensions & weight	
Width	1793 mm
Height	1831 mm
Length	4878 mm
Wheel base	2 mm
Kerb weight	1661 kg
Max. allowed weight	2290 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	DFSD232690