





report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO ACTIVE
Colour	Grey
Year of manufacture	2010
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 сс
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	Е



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-01-29

Pictures 9

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-10-04
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	9
Total items failed	8

MOT #14	2023-10-05 11:55
MOT test number	273140158234
Result	✓ Passed
Next expiry date	2024-10-04
Advice Exhaust has a minor leak of exhaust gases flexy joint (6.1.2 (a))	

MOT #13	2022-08-24 09:02
MOT test number	333958057966
Result	✓ Passed
MOT #12	2021-08-12 16:10
MOT test number	666033261487
Result	✓ Passed
MOT #11	2020-08-24 08:31

MOT test	number	669897871195
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Oil leak, but not excessive weeping (8.4.1 (a) (i))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #10 2019-07-30 15:47

MOT test number 649228852134

Result ✓ Passed

MOT #9 2019-07-30 11:11

MOT test number 737069800361

Result X Failed

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #8 2018-07-24 14:51

MOT test number 742803751483

Result ✓ Passed

MOT #7 2018-07-24 09:39

MOT test number 338786907292

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Position lamp switch does not illuminate the front and rear position lamps with a single operation

(4.2.2 (a))

MOT #6 2017-08-01 11:15

MOT test number 275765613305

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5

MOT test number

929110859662

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT test number

641371849588

Result

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Rear Exhaust has a major leak of exhaust gases silencer excessively corroded (7.1.2)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3

MOT test number

Result

Advice Tyre worn close to the legal limit (4.1.E.1)

Notice Outer skin exhaust slightly corroded

MOT #2	2014-08-04 10:55
MOT test number	868396114246
Result	✓ Passed
MOT #1	2013-08-08 11:37
MOT test number	476450323260
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	4 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner	hictory
OWITEI	HIISLULY

e when moterly	
For how long did the current and previous owner(s) have this FIAT? How many owners die Check it in the premium report and see all owner registrations. Download the full report is	
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDRESS	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	UK ZIN
Plate since	
Current registration	UK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-06-30
Last registration	2023-10-05
Complete history	See info



Registration #1	2010-06-30	11 mi
Registration #2	2013-08-08	31.851 mi
Registration #3	2014-08-04	42.870 mi
Registration #4	2015-08-03	55.521 mi
Registration #5	2016-08-02	67.591 mi
Registration #6	2016-08-02	67.591 mi
Registration #7	2017-08-01	79.188 mi
Registration #8	2018-07-24	90.327 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		0.00 44
Registration #15		11.777 es

7070.70.70

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number 5839116