





report date: 2024-03-28

General information

| Make | KIA |
|---------------------|----------------|
| Model | SOUL CRDI ECHO |
| Colour | Silver |
| Year of manufacture | 2011 |
| Top speed | 113 mph |
| 0 - 60 mph | 10.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 126 BHP |
|-------------------------|---------------------|
| Max. torque | 260 Nm at 1.900 rpm |
| Engine capacity | 1.582 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 44.8 mpg |
| Consumption extra urban | 61.4 mpg |
| Consumption combined | 45.6 mpg |
| CO2 emission | 137 g/km |
| CO2 label | E |



CarCheck.co.uk page 1/13



RE11RVO

report date: 2024-03-28

Internet history

Entry 1

Date 2021-10-18

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

| MOT expiry date | 2025-01-19 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 12 |
| Failed MOT tests | 4 |
| Total advice items | 14 |
| Total items failed | 10 |

| MOT #16 | 2024-01-19 17:10 |
|--|------------------|
| MOT test number | 750369962481 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-19 |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| MOT #15 | 2024-01-19 09:19 | |
|--|------------------|--|
| MOT test number | 703624739791 | |
| Result | X Failed | |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |
| Fail Battery insecure and likely to fall from carrier (4.13 (a) (ii)) | | |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | | |
| Pass with rectification Offside Headlamp aim too low (4.1.2 (a)) | | |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | | |
| Fail Nearside Rear Tyre has ply or cords damaged (5.2.3 (d) (ii)) | | |
| Pass with rectification Nearside Headlamp aim too low (4.1.2 (a)) | | |

| MOT #14 | 2023-01-20 12:19 |
|-----------------|------------------|
| MOT test number | 583479076823 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/13



MOT #13 2023-01-19 10:26

MOT test number 468576702250

Result X Failed

Fail Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Nearside Rear Position lamp not working (4.2.1 (a) (ii))

Advice Tyre worn close to legal limit/worn on edge Both fronts worn on edges (5.2.3 (e))

Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #12 2021-12-20 12:55

MOT test number 828309577641

MOT #11 2021-12-20 11:22

MOT test number 213265782035

Result X Failed

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #10 2021-09-02 13:41

MOT test number 896399324616

Result ✓ Passed

MOT #9 2020-09-03 07:19

MOT test number 558140778986

CarCheck.co.uk page 4/13



RE11RVO

report date: 2024-03-28

| MOT #8 | 2019-09-25 09:33 |
|--------|------------------|
| MOT #8 | 2019-09-25 09:3 |

MOT test number 191244349483

MOT #7 2019-04-08 12:31

MOT test number 154341635424

Result

Passed

MOT #6 2018-04-10 10:17

MOT test number 575140918613

Result
✓ Passed

Advice Offside Front TYRE WORN ON INNER EDGE

MOT #5 2017-04-24 16:04

MOT test number 465422226586

Result ✓ Passed

MOT #4 2016-05-27 10:30

MOT test number 835494586862

Result
✓ Passed

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Rear tyre slightly out of shape inner edge tyre perished in the tread

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

MOT #3 2015-05-15 16:06

MOT test number 767315935107

Result

Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/13



Result

RE11RVO report date: 2024-03-28

X Failed

MOT #2 2014-04-30 11:25

MOT test number 998350824123

Result ✓ Passed

Notice Child seat fitted not allowing full inspection of adult belt

MOT #1 2014-04-30 11:25

MOT test number 527170524108

Pass with rectification Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Notice Child seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 6/13



Tax & MOT check



| Tax status | Valid until 1 September |
|------------------|-------------------------|
| Days left | 126 |
| MOT expiry date | 19 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

| For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report h | |
|--|-------------|
| ******** | |
| *************************************** | |
| ************* | |
| *************************************** | |
| *************************************** | |
| ************* | |
| | More info > |
| Plate changes | |
| See in this check if this KIA had different number plates. | |
| Number of plates | , |
| Current registration | OK SIZ |
| Plate since | |
| Current registration | NK SIE |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 10/13



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 11/13



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 17 |
| First mileage registration | 2011-05-28 |
| Last registration | 2024-01-19 |
| Complete history | See info |



| Registration #1 | 2011-05-28 | 16 mi |
|--|------------|-------------|
| Registration #2 | 2014-04-30 | 36.872 mi |
| Registration #3 | 2015-05-15 | 54.185 mi |
| Registration #4 | 2016-05-27 | 67.133 mi |
| Registration #5 | 2017-04-24 | 75.699 mi |
| Registration #6 | 2018-04-10 | 82.768 mi |
| Registration #7 | 2019-04-08 | 89.161 mi |
| Registration #8 | 2019-09-25 | 92.650 mi |
| Deviatuation #0 | 2020 00 02 | 96.221 mi |
| Registration #9 | 2020-09-03 | 90.221 1111 |
| Registration #9 | 2020-09-03 | 90.221 1111 |
| | 2020-09-03 | 90.221 1111 |
| Registration #10 | 2020-09-03 | 90.221 1111 |
| Registration #10 Registration #11 | 2020-09-03 | 90.221 1111 |
| Registration #10 Registration #11 Registration #12 | 2020-09-03 | 90.221 1111 |
| Registration #10 Registration #11 Registration #12 Registration #13 | 2020-09-03 | 90.221 1111 |
| Registration #10 Registration #11 Registration #12 Registration #13 Registration #14 | 2020-09-03 | 90.221 1111 |

More info >

CarCheck.co.uk page 12/13



Car features

| 50225 | Air conditionin |
|-------|-----------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 60567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 87% |
| Children | 86% |
| Pedestrian | 39% |
| Safety systems | 86% |
| Overall rating | 77% |
| Video | see crash video |



Dimensions & weight

| Width | 1785 mm |
|---------------------|---------|
| Height | 1610 mm |
| Length | 4105 mm |
| Wheel base | 2550 mm |
| Kerb weight | 1429 kg |
| Max. allowed weight | 1780 kg |

Additional information

| Fuel tank capacity | 48 I | |
|-----------------------------------|------------------|------------|
| Fuel delivery | Direct Injection | |
| Number of doors | 5 | |
| Number of seats CarCheck.co.uk | 5 | page 13/13 |

Number of axles 2

Engine number D4FBAH532535