





General information

Make	HYUNDAI
Model	I30 CRDI SE BLUE DRIVE
Colour	Red
Year of manufacture	2016
Top speed	117 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	280 Nm at 1.500 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	83.1 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	А








Internet history

Entry 2	
Date	2021-01-29
Pictures	7
Listing price	View report



source: yesauto.com

Entry	1		
Date			

Pictures

Listing price


2021-01-22 7 <u>View report</u>



source: yesauto.com









MOT history

MOT expiry date	2025-04-11
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	9
Total items failed	5

MOT #8		2024-04-03 07:59
MOT test	number	349166077678
Result		Passed
Next expi	ry date	2025-04-11
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2024-04-03 07:59
MOT test number	941387250904
Result	× Failed
Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #6	2023-03-28 07:58
MOT test number	453120090644
Result	✓ Passed





MOT #5		2022-04-12 07:55
MOT test	number	837717616239
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4	2021-01-20 14:19
MOT test number	388804549401
Result	✓ Passed

МОТ #3	2020-03-10 09:47
MOT test number	889608800494
Result	🗸 Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #2	2020-03-07 10:20	
MOT test number	529624822369	
Result	🗙 Failed	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))	
Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))		
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.	6 (c))	
Pass with rectification Offside Headlamp aim too high (4.1.2 (a))		

MOT #1	2019-03-04 13:41
MOT test number	175947022502
Result	✓ Passed



Tax & MOT check

Tax due: 1 May 2025	✓ Taxed	Expires: 11 April 2025	✓ МОТ
1 May 2025		11 April 2025	
Tax status			Valid until 1 May
Days left			368
MOT expiry date			11 April 2025
Full MOT history			See MOT history
Tax calculation			
Vehicle class		49	
Band		А	

Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	
Plate since	
Current registration	
Rate sizes	





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-03-09
Last registration	2024-04-03
Complete history	See info



Registration #1	2016-03-09	24 mi
Registration #2	2019-03-04	34.543 mi
Registration #3	2020-03-07	55.095 mi
Registration #4	2020-03-10	55.114 mi
Registration #5	2021-01-20	56.876 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.117 esi





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Adult	90%
Children	90%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight	
Width	1780 mm
Height	1470 mm
Length	4300 mm
Wheel base	2650 mm
Kerb weight	1429 kg
Max. allowed weight	1920 kg
Additional information	
Fuel tank capacity	53
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	2
Engine number	D4FBGZ136218