





### General information

Make	MERCEDES
Model	CLK CLK280 SPORT
Colour	Black
Year of manufacture	2005
Top speed	150 mph
0 - 60 mph	7.8 seconds
Gearbox	7 speed automatic

### Engine & fuel consumption

Power	228 BHP
Max. torque	300 Nm at 3.000 rpm
Engine capacity	2.996 cc
Cylinders	6
Fuel type	Petrol
Consumption city	20.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	29.4 mpg
CO2 emission	229 g/km
CO2 label	L







# Internet history

Entry 1

Date Pictures 2021-07-17

Listing price

View report

12









source: autotrader.co.uk



# MOT history

MOT expiry date	2024-12-12
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	31
Total items failed	9

MOT #22		2023-12-13 11:37
MOT test	number	332952456063
Result		🗸 Passed
Next expi	ry date	2024-12-12
Advice	Rear Coil spring corroded all rear suspension components corroded (5.3.1 (b) (	i))
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))		(1.1.14 (a) (ii))
Advice	All rear suspension components corroded	

MOT #21	2022-10-10 10:56
MOT test number	719594963979
Result	✓ Passed
Advice P[ower steering pump noisy however steering not adversely affected	

MOT #20		2021-05-06 13:13
MOT test i	number	483715620224
Result		✓ Passed
Advice	Offside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))	





MOT #19		2020-05-13 10:16
MOT test	number	204084023452
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (	5.2.3 (d) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1	.1.14 (a) (ii))

MOT #18		2019-09-13 15:48
MOT test	number	586204268557
Result		✓ Passed
Advice	Surface corrosion on rear underside of floor	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))
<b>Advice</b> (5.3.4 (a)	Nearside Front Lower Suspension arm pin or bush worn but not resulting in e (i))	excessive movement
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1	1.11 (c))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened	d (1.1.14 (a) (ii))
Advice	Under trays fitted	
<b>Advice</b> (5.3.4 (a)	Offside Front Lower Suspension arm pin or bush worn but not resulting in ex (i))	cessive movement
<b>Minor</b> (a) (i))	All position lamps with a multiple light source up to 1/2 not functioning High l	evel brake light (4.2.1
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.3	11 (c))





MOT #17	2018-09-10 15:04	
MOT test number	406021819485	
Result	✓ Passed	
Minor Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (	4.3.1 (a) (i))	
MOT #16	2018-09-10 11:26	
MOT test number	439901791687	
Result	× Failed	
<b>Fail</b> Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))		
Fail         Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))		
Minor Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (	4.3.1 (a) (i))	

MOT #15	2017-09-07 09:14
MOT test number	565132963596
Result	✓ Passed

MOT #14	2016-09-12 12:41
MOT test number	805938395419
Result	✓ Passed

MOT #13	2016-09-08 15:58
MOT test number	280582550663
Result	🗙 Failed
Fail         Nearside Front coil spring broken (2.4.C.1a)	
Advice Engine management light on	
Fail         Offside Rear Direction indicator incorrect colour (1.4.A.2f)	





MOT #12	2015-08-20 14:04
MOT test number	555879225097
Result	✓ Passed
MOT #11	2014-08-29 15:32
MOT test number	159331244293
Result	✓ Passed

MOT #10	2014-08-29 10:32
MOT test number	148071544288
Result	🗙 Failed
<b>Fail</b> Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
<b>Fail</b> Centre Stop lamp not working (1.2.1b)	

MOT #9	2013-09-07 10:32
MOT test number	259160753291
Result	✓ Passed

MOT #8		2012-08-16 10:42
MOT test	number	375419222407
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #7	2011-08-19 11:41
MOT test number	397751231431
Result	✓ Passed





MOT #6		2011-08-19 11:41
MOT test number		388431431203
Result		🗙 Failed
Pass with rectification	Nearside Headlamp aim too high (1.8)	
Pass with rectification	Offside Headlamp aim too high (1.8)	

MOT #5	2010-09-09 13:53
MOT test number	614732250273
Result	✓ Passed

MOT #4		2010-01-18 11:53
MOT test	number	673558410050
Result		✓ Passed
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
<b>Advice</b> Rear Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)		

МОТ #3	2009-01-30 13:54
MOT test number	192130039479
Result	✓ Passed
<b>Notice</b> Rear tyres showing sgns of wear	

MOT #2	2008-02-01 13:41
MOT test number	142062638000
Result	✓ Passed





MOT #1		2008-02-01 13:41
MOT test number		610332138027
Result		🗙 Failed
Pass with rectification	Front registration plate missing (6.3.1a)	



Tax & MOT check

✓ Taxed Tax due: 1 December 2024	✓ MOT Expires: 12 December 2024
Tax status	Valid until 1 December
Days left	215
MOT expiry date	12 December 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





#### Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	AMP
Туре	A CONTRACT
Damage 2	AMPLE
Date	
Category	AMPT
Туре	

#### Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





#### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
********	
and the second	
***********	
**********	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-09-30
Last registration	2023-12-13
Complete history	<u>See info</u>



Registration #2       2008-02-01       24.02         Registration #3       2009-01-30       36.80         Registration #4       2010-01-18       47.49         Registration #5       2010-09-09       51.65         Registration #6       2011-08-19       54.25         Registration #6       2013-09-07       59.48         Registration #8       2013-09-07       59.48         Registration #10       2014-08-29       62.43         Registration #11       2015-08-20       64.29         Registration #12       Image: Stration #13       Image: Stration #14         Registration #14       Image: Stration #15       Image: Stration #16       Image: Stration #17         Registration #18       Image: Stration #18       Image: Stration #19       Image: Stration #19         Registration #19       Image: Stration #19       Image: Stration #10       Image: Stration #10       Image: Stration #10         Registration #16       Image: Stration #16       Image: Stration #17       Image: Stration #10       Image: Stration #10         Registration #19       Image: Stration #10       Image: Stration #10       Image: Stration #10       Image: Stration #10         Registration #16       Image: Stration #10       Image: Stration #10       Image: Stration #10       <			
Registration #3       2009-01-30       36.80         Registration #4       2010-01-18       47.49         Registration #5       2010-09-09       51.65         Registration #6       2011-08-19       54.25         Registration #7       2012-08-16       56.78         Registration #7       2012-08-16       56.78         Registration #8       2013-09-07       59.48         Registration #9       2014-08-29       62.43         Registration #10       2015-08-20       64.29         Registration #11       2015-08-20       64.29         Registration #12       T       T         Registration #13       T       T         Registration #14       T       T         Registration #15       T       T         Registration #16       T       T         Registration #17       T       T         Registration #18       E       T         Registration #19       T       T         Registration #20       E       T	Registration #1	2005-09-30	22 mi
Registration #4       2010-01-18       47.49         Registration #5       2010-09-09       51.65         Registration #6       2011-08-19       54.25         Registration #7       2012-08-16       56.78         Registration #8       2013-09-07       59.48         Registration #9       2014-08-29       62.43         Registration #10       2015-08-20       64.29         Registration #11       2015-08-20       64.29         Registration #12       Italian       Italian         Registration #13       Italian       Italian         Registration #14       Italian       Italian         Registration #15       Italian       Italian         Registration #16       Italian       Italian         Registration #18       Italian       Italian         Registration #19       Italian       Italian         Registration #19       Italian       Italian         Registration #19       Italian       Italian         Registration #20       Italian       Italian	Registration #2	2008-02-01	24.024 mi
Registration #5       2010-09-09       51.65         Registration #6       2011-08-19       54.25         Registration #7       2012-08-16       56.78         Registration #8       2013-09-07       59.48         Registration #9       2014-08-29       62.43         Registration #10       2014-08-29       62.43         Registration #11       2015-08-20       64.29         Registration #12       1       1         Registration #13       1       1         Registration #14       1       1         Registration #15       1       1         Registration #16       1       1         Registration #18       1       1         Registration #19       1       1	Registration #3	2009-01-30	36.800 mi
Registration #6       2011-08-19       54.25         Registration #7       2012-08-16       56.78         Registration #8       2013-09-07       59.48         Registration #9       2014-08-29       62.43         Registration #10       2015-08-20       64.29         Registration #11       2015-08-20       64.29         Registration #12       1       1         Registration #13       1       1         Registration #14       1       1       1         Registration #15       1       1       1       1         Registration #16       1 <th>Registration #4</th> <th>2010-01-18</th> <th>47.492 mi</th>	Registration #4	2010-01-18	47.492 mi
Registration #7       2012-08-16       56.78         Registration #8       2013-09-07       59.48         Registration #9       2014-08-29       62.43         Registration #10       2014-08-29       62.43         Registration #11       2015-08-20       64.29         Registration #11       2015-08-20       64.29         Registration #12	Registration #5	2010-09-09	51.651 mi
Registration #8       2013-09-07       59.48         Registration #9       2014-08-29       62.43         Registration #10       2014-08-29       62.43         Registration #11       2015-08-20       64.29         Registration #12       1       1         Registration #13       2       1         Registration #14       1       1       1         Registration #15       1       1       1         Registration #16       1       1       1       1         Registration #18       1	Registration #6	2011-08-19	54.256 mi
Registration #92014-08-2962.43Registration #102014-08-2962.43Registration #112015-08-2064.29Registration #12Registration #13Registration #14Registration #15Registration #16Registration #17Registration #18Registration #19Registration #20	Registration #7	2012-08-16	56.789 mi
Registration #102014-08-2962.43Registration #112015-08-2064.29Registration #12Registration #13Registration #14Registration #15Registration #16Registration #17Registration #18Registration #19Registration #20	Registration #8	2013-09-07	59.489 mi
Registration #112015-08-2064.29Registration #12Registration #13Registration #13Registration #14Registration #14Registration #14Registration #15Registration #15Registration #16Registration #16Registration #17Registration #17Registration #18Registration #19Registration #19Registration #20Image: State of	Registration #9	2014-08-29	62.431 mi
Registration #12Registration #13Registration #14Registration #15Registration #16Registration #17Registration #18Registration #19Registration #20	Registration #10	2014-08-29	62.431 mi
Registration #13Registration #14Registration #15Registration #16Registration #16Registration #17Registration #18Registration #19Registration #20	Registration #11	2015-08-20	64.290 mi
Registration #14   Registration #15   Registration #16   Registration #17   Registration #18   Registration #19   Registration #20	Registration #12		11.777 esi
Registration #15Registration #16Registration #17Registration #18Registration #19Registration #20	Registration #13		11.777 esi
Registration #16 Registration #17 Registration #18 Registration #19 Registration #20	Registration #14		11.777 esi
Registration #17 Registration #18 Registration #19 Registration #20	Registration #15		11.777 esi
Registration #18 Registration #19 Registration #20	Registration #16		11.777 esi
Registration #19 Registration #20	Registration #17		11.777 esi
Registration #20	Registration #18		11.777 esi
	Registration #19		11.777 esi
Registration #21	Registration #20		11.117 est
	Registration #21		11.117 esi
	Registration #22		10.000 est

More info  $\rightarrow$ 



## Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2690 mm
Kerb weight	1705 kg
Max. allowed weight	2170 kg

## Additional information

Fuel tank capacity	62
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27294030218464