





report date: 2024-03-29

General information

Make	FIAT
Model	500 C POP
Colour	White
Year of manufacture	2011
Top speed	107 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	145 Nm at 1.900 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	95 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 4

Date 2021-10-01

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 3

Date	2021-07-25
------	------------

Pictures 18

Listing price <u>View report</u>









source: yesauto.com

Entry 2

Date 2021-07-16

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk



report date: 2024-03-29

MOT history

MOT expiry date	2024-10-02
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	9
Total items failed	2

MOT #13	2023-10-03 08:41	
MOT test number	242512439448	
Result	✓ Passed	
Next expiry date	2024-10-02	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		

MOT #12	2023-10-02 09:20
MOT test number	409185388123
Result	🗙 Failed
Fail Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) ((ii))

MOT #11	2022-09-21 07:30
MOT test number	362665424545
Result	✓ Passed
MOT #10	2022-06-09 13:27
MOT test number	669679884384
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #9	2022-06-07 18:09
MOT test number	814737987093
Result	× Failed
Fail Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))	

MOT #8		2021-06-11 12:05
MOT test	number	716204170590
Result		✓ Passed
MOT #7		2020-06-17 08:50
MOT test	number	710290605279
Result		✓ Passed
Advice	Offside Rear Nail in tyre	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #6	2019-06-14 06:19
MOT test number	667934293315
Result	✓ Passed
MOT #5	2018-06-18 12:36
MOT test number	458920800071
Result	√ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4		2017-04-22 09:31
MOT test	number	176048416898
Result		✓ Passed
Advice	Nearside Front Shock absorber has a light misting of oil (2.7.3)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Front Wing damage	

MOT #3	2016-04-23 08:19
MOT test number	814495645158
Result	✓ Passed
Advice Front brake discs corrosion	

MOT #2	2015-04-27 11:37
MOT test number	675937215135
Result	✓ Passed

MOT #1	2014-11-28 09:28
MOT test number	348512934379
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	2 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

RO11BWW

report date: 2024-03-29

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

More info >



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-04-30
Last registration	2023-10-03
Complete history	See info



Registration #1	2011-04-30	9 mi
Registration #2	2014-11-28	19.566 mi
Registration #3	2015-04-27	19.581 mi
Registration #4	2016-04-23	30.648 mi
Registration #5	2017-04-22	39.719 mi
Registration #6	2018-06-18	48.829 mi
Registration #7	2019-06-14	51.601 mi
Registration #8	2020-06-17	53.271 mi
Registration #9	2021-06-11	54.424 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	930 kg
Max. allowed weight	1370 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine number0012511