





report date: 2024-03-28

General information

Make	VOLVO	
Model	V40 D2 R-DESIGN NAV PLUS	
Colour	Silver	
Year of manufacture	2017	
Top speed	118 mph	
0 - 60 mph	9.8 seconds	
Gearbox	6 speed Manual	

Engine & fuel consumption

Power	120 BHP
Max. torque	280 Nm at 2.250 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption combined	83.1 mpg
CO2 emission	94 g/km
CO2 label	A



CarCheck.co.uk page 1/12



Internet history

Entry 1


Date 2021-02-06

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



LO17KBX

report date: 2024-03-28

MOT history

MOT expiry date	2025-03-21
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	14
Total items failed	0

MOT #10	2024-03-12 16:38
MOT test number	884376760744
Result	✓ Passed
Next expiry date	2025-03-21

MOT #9		2024-03-12 09:59
MOT test number	er	881741687521
Result		X Failed
DANGEROUS (5.2.3 (e))	Nearside Front Inner Tyre tread depth below requirements of 1.6mm	edge badly worn
DANGEROUS	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
DANGEROUS	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	

MOT #8	2023-03-14 16:41
MOT test number	233760916054
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/12



LO17KBX

report date: 2024-03-28

MOT #7 2023-03-14 10:25

MOT test number 237022637864

Result X Failed

DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

DANGEROUS Front Tyre has ply or cords exposed both (5.2.3 (d) (ii))

MAJOR Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6 2022-03-08 12:05

MOT test number 657194245366

Result \(\sqrt{Passed} \)

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #5 2022-03-08 10:22

MOT test number 792635636717

Result × Failed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

DANGEROUS Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #4 2021-03-22 13:49

MOT test number 828324054101

Result ✓ Passed

MOT #3 2020-09-01 10:35

MOT test number 797375180681

Result
✓ Passed

CarCheck.co.uk page 4/12



 MOT #2
 2020-08-28 07:57

 MOT test number
 300381491560

 Result
 X Failed

MAJOR Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

MOT #1

MOT test number

853473451703

Result

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	21 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
First licence fee (12 months)	£ 165,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



LO17KBX

report date: 2024-03-28

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner History	
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2017-05-31
Last registration	2024-03-12
Complete history	See info



Registration #1	2017-05-31	21 mi
Registration #2	2020-08-28	67.678 mi
Registration #3	2020-09-01	67.679 mi
Registration #4		11.177 es
Registration #5	2021-03-22	67.685 mi
Registration #6	2022-03-08	76.468 mi
Registration #7		11.777 es
Registration #8		71.777 es
Registration #9		11.177 es
Registration #10		11.177 es
Registration #11		71.777 mg

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	2041 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1382 kg
Max. allowed weight	1920 kg

Additional information

Fuel tank capacity	40 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1	2/12

Engine number

2060052