



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS C-MAX TITANIUM D
Colour	Black
Year of manufacture	-
Top speed	126 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	340 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	51.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-21
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT #21	2021-07-30 08:54
MOT test number	124776800430
Result	✓ Passed
Next expiry date	2022-08-21
Advice	Rear exhaust mounting broken and some corrosion to system
Advice	Engine lower cover partly secured

MOT #20	2021-07-30 08:54
MOT test number	644549486802
Result	✗ Failed
Advice	Rear exhaust mounting broken and some corrosion to system
Pass with rectification	Nearside Front Direction indicator incorrect colour (4.4.3 (a))
Advice	Engine lower cover partly secured
Pass with rectification	Offside Front Direction indicator incorrect colour (4.4.3 (a))

MOT #19	2020-08-22 12:14
MOT test number	627662663130
Result	✓ Passed
Advice	Hydraulic leak, but not excessive Steering rack slight seepage (8.4.1 (a) (i))
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Rear exhaust bracket broken but still secure

MOT #18	2019-07-30 14:02
MOT test number	144640265862
Result	✓ Passed
Advice	Hydraulic leak, but not excessive Steering rack slight seepage (8.4.1 (a) (i))

**MOT #17**

2019-07-30 09:14

MOT test number

607768154554

Result**✗ Failed**

- Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Offside Front Headlamp levelling device inoperative (4.1.5 (a))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 205/55/16 (5.2.3 (d) (i))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Hydraulic leak, but not excessive Steering rack slight seepage (8.4.1 (a) (i))

MOT #16

2018-07-27 11:33

MOT test number

580245787761

Result**✓ Passed**

- Advice** Both rear tyres slightly out of shape
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm rear bush (5.3.4 (a) (i))

MOT #15

2017-07-24 09:31

MOT test number

702061105132

Result**✓ Passed****MOT #14**

2016-07-27 15:11

MOT test number

928949949070

Result**✓ Passed**

**MOT #13** 2016-07-27 11:21**MOT test number** 575294276069**Result** ✗ Failed**Fail** Offside Front Steering rack gaiter split (2.2.D.2d)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**MOT #12** 2015-07-15 14:40**MOT test number** 848456095159**Result** ✓ Passed**MOT #11** 2015-07-14 11:21**MOT test number** 335105195161**Result** ✗ Failed**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Fail** Offside Front Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)**Fail** Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #10** 2014-07-23 16:56**MOT test number** 116944504208**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in offside rear tyre**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2013-07-13 10:57**MOT test number** 969224393128**Result** ✓ Passed**MOT #8** 2013-07-11 10:58**MOT test number** 909622093125**Result** ✗ Failed**Fail** Offside Front Upper Tie bar/rod ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #7** 2012-07-18 11:01**MOT test number** 685940302258**Result** ✓ Passed**MOT #6** 2011-07-30 10:36**MOT test number** 605651211223**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2011-07-30 10:36**MOT test number** 565641811236**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #4** 2010-07-26 08:17**MOT test number** 882187100269**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2009-07-17 10:24**MOT test number** 230078599430**Result** ✓ Passed**MOT #2** 2008-08-06 08:36**MOT test number** 744779518262**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2008-08-06 08:36**MOT test number** 370699718424**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	LX05NNE
Plate since	2019-03-29
Current registration	LX05NNE
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-07-16
Last registration	2021-07-30
Complete history	See info



Registration #1	2005-07-16	27 mi
Registration #2	2008-08-06	26.184 mi
Registration #3	2009-07-17	32.861 mi
Registration #4	2010-07-26	39.065 mi
Registration #5	2011-07-30	46.405 mi
Registration #6	2012-07-18	53.856 mi
Registration #7	2013-07-11	61.038 mi
Registration #8	2013-07-13	61.071 mi
Registration #9	2014-07-23	70.020 mi
Registration #10	2015-07-14	76.567 mi
Registration #11	2015-07-15	76.567 mi
Registration #12	2016-07-15	83.114 mi
Registration #13	2017-07-15	89.661 mi
Registration #14	2018-07-15	96.208 mi
Registration #15	2019-07-15	102.755 mi
Registration #16	2020-07-15	109.302 mi
Registration #17	2021-07-15	115.849 mi
Registration #18	2022-07-15	122.396 mi
Registration #19	2023-07-15	128.943 mi
Registration #20	2024-07-15	135.490 mi
Registration #21	2025-07-15	142.037 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1991 mm
Height	1447 mm
Length	4382 mm
Wheel base	2640 mm
Kerb weight	1276 kg
Max. allowed weight	1895 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	5U29666
---------------	---------