



GK55WKT

report date: 2024-03-28

General information

Make	FORD
Model	FOCUS C-MAX ZETEC TDCI
Colour	Silver
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	11.9 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	108 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg





Internet history

Entry 1

Date	2021-09-03
Pictures	18
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #14	2020-11-18 14:16
MOT test number	845489023858
Result	✓ Passed
Next expiry date	2021-11-17
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #13	2019-08-06 13:03
MOT test number	804377777916
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Front Windscreen wiper blade defective (3.4 (b) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2019-08-02 13:12

MOT test number

129857601065

Result**✗ Failed**

- Fail** Nearside Front Headlamp lens seriously defective (4.1.1 (b) (ii))
- Fail** Exhaust emits excessive smoke or vapour likely to obscure the vision of other road users (8.2.2.2 (c))
- Fail** Nearside Front Headlamp aim not tested (4.1.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Emissions not tested (8.2.2.2 (e))
- Fail** Offside Front Headlamp lens seriously defective (4.1.1 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Headlamp aim not tested (4.1.2 (b))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))
- Minor** Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #11

2018-07-16 10:15

MOT test number

818222146558

Result**✓ Passed**

- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**MOT #10** 2017-07-10 10:15**MOT test number** 338519137293**Result** ✓ Passed**MOT #9** 2016-07-12 10:15**MOT test number** 513221055394**Result** ✓ Passed**Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)**MOT #8** 2015-07-20 12:19**MOT test number** 755791305293**Result** ✓ Passed**Advice** Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2014-07-16 11:01**MOT test number** 348507094198**Result** ✓ Passed**MOT #6** 2013-07-22 11:16**MOT test number** 719013903265**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #5	2012-07-23 11:32
MOT test number	196495602224
Result	✓ Passed
Advice	Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
MOT #4	2011-08-19 11:19
MOT test number	827001431231
Result	✓ Passed
MOT #3	2010-08-13 11:12
MOT test number	650785120286
Result	✓ Passed
MOT #2	2009-08-14 10:48
MOT test number	300526929213
Result	✓ Passed
MOT #1	2008-08-13 10:56
MOT test number	332816228461
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2005-09-09
Last registration	2020-11-18
Complete history	See info



Registration #1	2005-09-09	7 mi
Registration #2	2008-08-13	23.486 mi
Registration #3	2009-08-14	27.798 mi
Registration #4	2010-08-13	30.874 mi
Registration #5	2011-08-19	34.562 mi
Registration #6	2012-07-23	37.645 mi
Registration #7	2013-07-22	39.738 mi
Registration #8	2014-07-16	42.338 mi
Registration #9	2015-05-20	45.277 mi
Registration #10	2016-05-20	48.277 mi
Registration #11	2017-05-20	51.277 mi
Registration #12	2018-05-20	54.277 mi
Registration #13	2019-05-20	57.277 mi
Registration #14	2020-05-20	60.277 mi
Registration #15	2021-05-20	63.277 mi
Registration #16	2022-05-20	66.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1449 kg
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

5K80779