





report date: 2024-03-28

General information

Make	HYUNDAI
Model	140 CRDI ACTIVE BLUE DRIVE
Colour	Silver
Year of manufacture	2012
Top speed	119 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/13



RE62AXY report date: 2024-03-28

MOT history

MOT expiry date	2024-07-02
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	12
Total items failed	10

MOT #14	2023-07-03 09:49
MOT test number	247124417073
Result	✓ Passed
Next expiry date	2024-07-02
Advice Steering rack has slight free play detected at steering wheel (2.3 (a) (i))	

MOT #13	2023-02-15 15:01
MOT test number	617473125860
Result	✓ Passed
Advice Upper Steering column universal joint has slight wear or play (2.2.2 (c))	

MOT #12	2022-03-01 13:07
MOT test number	329000899060
Result	✓ Passed
Advice Rear Brake hose has slight corrosion to ferrule both (1.1.12 (f) (i))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #11 2022-02-25 12:43

MOT test number 386408783065

Result X Failed

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Offside Front Brake pipe excessively corroded (1.1.11 (c))

Fail Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))

Fail Offside Brake pipe excessively corroded main at rear (1.1.11 (c))

Advice Rear Brake hose has slight corrosion to ferrule both (1.1.12 (f) (i))

MOT #10 2021-03-03 13:58

MOT test number 905536204929

Result ✓ Passed

MOT #9 2020-07-07 12:58

MOT test number 285653826429

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #8 2020-07-07 09:44 **MOT** test number 633786108196 Result × Failed Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) Fail Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Windscreen washer provides insufficient washer liquid (3.5 (a)) Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #7	2019-04-23 10:24
MOT test number	637872215359
Result	✓ Passed
MOT #6	2019-04-23 09:10
MOT test number	972021542242
Result	X Failed
Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #5	2018-04-19 12:55
MOT test number	261407345327
Result	✓ Passed

CarCheck.co.uk page 5/13



RE62AXY report date: 2024-03-28

Passed

MOT #4 2018-04-19 08:54

MOT test number 541546517055

Result × Failed

Fail Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)

MOT #3 2017-04-24 15:31

MOT test number 719707530005

Result ✓ Passed

MOT #2 2016-04-26 08:28

MOT test number 152863008728

Result ✓ Passed

MOT #1 2015-04-25 10:45

MOT test number 898085215183

Result

Notice Under-trays fitted obscuring some underside components

CarCheck.co.uk page 6/13



RE62AXY report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	2 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

RE62AXY

report date: 2024-03-28

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here.

Plate changes

More info >

More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >


CarCheck.co.uk page 11/13



RE62AXY report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-10-01
Last registration	2023-07-03
Complete history	See info



Registration #1	2012-10-01	17 mi
Registration #2	2015-04-25	17.044 mi
Registration #3	2016-04-26	23.215 mi
Registration #4	2017-04-24	29.109 mi
Registration #5	2018-04-19	36.759 mi
Registration #6	2018-04-19	36.759 mi
Registration #7	2019-04-23	43.624 mi
Registration #8	2019-04-23	43.625 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.177 es
Registration #12		11.177 es
Registration #13		11.177 es
Registration #14		11.177 es
Registration #15		11.777 es
Registration #16		10.777 au

More info >

page 12/13 CarCheck.co.uk



RE62AXY report date: 2024-03-28

Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4740 mm
Wheel base	2770 mm
Kerb weight	1601 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2

Engine number D4FDCU100418