






report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA HDI DESIRE 2 PICASSO
Colour	Red
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	205 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	51.4 mpg



CarCheck.co.uk page 1/12



CK04MTZ report date: 2024-03-28

Internet history

Entry 1

Date 2021-12-03

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



CK04MTZ report date: 2024-03-28

MOT history

MOT #19 2021-12-01 14:31

MOT test number 637650994346

Result
✓ Passed

Next expiry date 2022-11-30

MOT #18 2021-01-20 13:42

MOT test number 469421081300

Result \rightarrow Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #17 2020-01-27 17:15

MOT test number 248828976529

Result ✓ Passed

MOT #16 2019-01-29 16:13

MOT test number 814872205762

Result \(\sqrt{Passed} \)

Advice Exhaust back box hanger deteriorated but system still adequately supported

MOT #15 2018-01-30 13:39

MOT test number 387518193012

Result \(\sqrt{Passed} \)

Advice Nearside Rear Tyre worn close to the legal limit bald on edges (4.1.E.1)

Advice Offside rear tyre worn on edges

MOT #14 2017-01-18 10:01

MOT test number 654407159399

Result
✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #13 2016-02-01 12:59

MOT test number 669410634931

MOT #12 2016-02-01 11:31

MOT test number 107725398198

Result X Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm outer edge (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit on limit on outer edge (4.1.E.1)

MOT #11 2015-02-04 14:40

MOT test number 177485235408

Result \(\sqrt{Passed} \)

MOT #10 2015-02-04 11:16

MOT test number 425035835029

Result X Failed

Fail Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

MOT #9 2014-01-29 13:32

MOT test number 506129224094

MOT #8 2013-01-23 14:48

MOT test number 749303623089

Result
✓ Passed

MOT #7 2012-02-16 16:47

MOT test number 287367342035

Result

Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number

Result

Fail Nearside Side repeater incorrect colour (1.4.A.2f)

Fail Nearside Rear Direction indicators incorrect colour (1.4.A.2f)

Fail Offside Side repeater incorrect colour (1.4.A.2f)

MOT #5 2011-05-13 13:40 **MOT** test number 306013131178 Result ✓ Passed **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1) Notice Oil level low **Advice** Offside Side repeater slightly discoloured (1.4.A.2f) Notice Offside front tyre worn on inner and outer edges **Advice** Nearside Side repeater slightly discoloured (1.4.A.2f)

MOT #4

MOT test number

Fesult

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



report date: 2024-03-28

MOT #2		2008-04-28 16:39
MOT test	number	540599418104
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Seat belt pre-tensioner has been activated	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Child seat fitted not allowing full inspection of adult belt	

MOT #1	2007-02-26 16:04
MOT test number	271587457060
Result	✓ Passed

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



CKO4MTZ report date: 2024-03-28

Owner history

e when miscory		
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full in		OEN

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



CK04MTZ report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-03-31
Last registration	2021-12-01
Complete history	See info



Registration #1	2004-03-31	13 mi
Registration #2	2007-02-26	21.888 mi
Registration #3	2008-04-28	33.045 mi
Registration #4	2009-04-24	40.803 mi
Registration #5	2010-05-10	50.836 mi
Registration #6	2011-05-13	60.522 mi
Registration #7	2012-02-14	64.615 mi
Registration #8	2012-02-16	64.615 mi
Registration #9	2013-01-23	72.981 mi
Registration #10	2014-01-29	82.031 mi
Registration #11	2015-02-04	90.555 mi
Registration #12		11.117 es
Registration #13		11.777 es
Registration #14		77.777 ea
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11,177 es

More info >

CarCheck.co.uk page 11/12



CKO4MTZ
report date: 2024-03-28

Safety ratings

NCAP rating

Video <u>see crash video</u>

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Engine number	DYRZ4017511

CarCheck.co.uk page 12/12