



report date: 2024-03-28

General information

Make	LAND ROVER
Model	RANGE ROVER TDV8 VOGUE SE
Colour	Gold
Year of manufacture	2011
Top speed	130 mph
0 - 100 km/h	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	230 kW / 313 HP / 313 BHP
Max. torque	700 Nm at 1.500 rpm
Engine capacity	4.367 cc
Cylinders	8
Fuel type	Diesel
Consumption city	24.6 mpg
Consumption extra urban	34.5 mpg
Consumption combined	30.1 mpg
CO2 emission	253 g/km
CO2 label	L





Internet history

Entry 2

Date	2021-09-11
Pictures	1
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-09-10
Pictures	6
Listing price	View report



source: cargurus.co.uk





MOT history

MOT expiry date	2024-07-06
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	26
Total items failed	18

MOT #15	2023-07-07 10:44
MOT test number	140692936390
Result	✓ Passed
Next expiry date	2024-07-06

MOT #14	2022-07-07 13:35
MOT test number	623411506684
Result	✓ Passed

MOT #13	2022-06-28 10:51
MOT test number	266622040541
Result	✗ Failed
Fail	Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
Fail	Offside Front Brake pipe excessively corroded (1.1.11 (c))
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Nearside Front Brake pipe excessively corroded (1.1.11 (c))
Fail	Oil leaking excessively from engine (8.4.1 (a) (i))
Fail	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #12**

2021-12-21 15:51

MOT test number

875929925969

Result

✓ Passed

Advice

Brake pipe corroded, covered in grease or other material Front and rear (1.1.11 (c))

MOT #11

2020-05-14 14:27

MOT test number

861618443652

Result

✓ Passed

Advice

Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Advice

Brake pipe corroded, covered in grease or other material Front to Offside rear pipe (1.1.11 (c))

Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Brake pipe corroded, covered in grease or other material Front to Nearside rear pipe (1.1.11 (c))

**MOT #10**

2020-05-13 09:54

MOT test number

190679783718

Result**✗ Failed**

- Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Brake pipe corroded, covered in grease or other material Front to Offside rear pipe (1.1.11 (c))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Fail** Offside Rear Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))
- Advice** Brake pipe corroded, covered in grease or other material Front to Nearside rear pipe (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Brake performance not tested (1.2.1 (g))

MOT #9

2019-05-11 10:43

MOT test number

802519861376

Result**✓ Passed**

- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**MOT #8** 2019-05-10 14:12**MOT test number** 483143129058**Result** ✗ Failed**Fail** Offside Front Suspension arm pin or bush excessively worn rear arm inner bush (5.3.4 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Nearside Front Suspension arm pin or bush excessively worn rear arm inner bush (5.3.4 (a) (i))**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #7** 2018-05-22 06:43**MOT test number** 150506674525**Result** ✓ Passed**MOT #6** 2018-05-18 11:53**MOT test number** 850834346207**Result** ✗ Failed**Fail** Offside Rear reflector missing (1.5.1a)**Advice** Nearside Rear Nail in tyre**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Nail in tyre**Advice** Oil leak**MOT #5** 2017-05-20 07:39**MOT test number** 771174490646**Result** ✓ Passed

**MOT #4** 2017-05-19 14:55**MOT test number** 511299086391**Result** ✗ Failed**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #3** 2016-10-19 16:02**MOT test number** 426368139271**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin 3-4mm (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Rear Brake pad(s) wearing thin 3-4mm (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2015-09-08 10:15**MOT test number** 417480290791**Result** ✓ Passed**MOT #1** 2014-09-18 15:59**MOT test number** 739071464287**Result** ✓ Passed**Notice** Emissions too clean to test



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
6 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	6 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-09-14
Last registration	2023-07-07
Complete history	See info



Registration #1	2011-09-14	10 mi
Registration #2	2014-09-18	53.253 mi
Registration #3	2015-09-08	63.834 mi
Registration #4	2016-10-19	75.156 mi
Registration #5	2017-05-19	79.009 mi
Registration #6	2017-05-20	79.009 mi
Registration #7	2018-05-18	83.739 mi
Registration #8	2018-05-22	83.739 mi
Registration #9	2019-05-10	88.747 mi
Registration #10	2019-05-20	93.757 mi
Registration #11	2019-05-20	93.757 mi
Registration #12	2019-05-20	93.757 mi
Registration #13	2019-05-20	93.757 mi
Registration #14	2019-05-20	93.757 mi
Registration #15	2019-05-20	93.757 mi
Registration #16	2019-05-20	93.757 mi
Registration #17	2019-05-20	93.757 mi
Registration #18	2019-05-20	93.757 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2216 mm
Height	1865 mm
Length	4967 mm
Wheel base	2880 mm
Kerb weight	2710 kg
Max. allowed weight	3200 kg

Additional information

Fuel tank capacity	100 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	0006899448DT