





report date: 2024-03-29

General information

Make	PEUGEOT
Model	5008 HDI ALLURE
Colour	Blue
Year of manufacture	2013
Top speed	115 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP	
Max. torque	270 Nm at 1.750 rpm	
Engine capacity	1.560 cc	
Cylinders	4	
Fuel type	Diesel	
Consumption city	45.6 mpg	
Consumption extra urban	61.4 mpg	
Consumption combined	54.3 mpg	
CO2 emission	135 g/km	
CO2 label	E	



CarCheck.co.uk page 1/12



KM13NME report date: 2024-03-29

Internet history

Entry 2

Listing price

Date	2021-10-27
Pictures	1

View report



source: cargurus.co.uk

Entry 1

Date	2021-10-26	
Pictures	1	
Listing price	<u>View report</u>	



source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2024-09-16
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	23
Total items failed	1

MOT #10		2023-09-13 07:45
MOT test	number	352212013544
Result		✓ Passed
Next expi	ry date	2024-09-16
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Exhaust tail box heatshield insecure	
Advice	Nearside Front lower dust cover shield insecure	

MOT #9	2022-09-12 11:29
MOT test number	551935261076
Result	✓ Passed
MOT #8	2021-09-17 10:54
MOT test number	618732163607
Result	✓ Passed

MOT #7	2020-09-16 09:10
MOT test number	852277638480
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #6 2019-04-24 15:08

MOT test number 562566990257

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #5 2019-04-23 12:05

MOT test number 799861321565

Result X Failed

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Windscreen washer not working (3.5 (a))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MAJOR Nearside Front Position lamp not working (4.2.1 (a))

DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #4 2018-04-30 08:34

MOT test number 264689988592

Result \(\sqrt{Passed} \)

Advice Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

Advice Offside Rear brake slight bind

Advice Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT test number

Result

Advice Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

Advice Offside Rear brake slight bind

Advice Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

Pass with rectification Offside Front Headlamp aim too high (1.8)

MOT #2

MOT test number

107693398103

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT test number

Result

Advice Front Tyre worn close to the legal limit both sides worn (4.1.E.1)

Advice Oil leak

Advice Rear Brake pad(s) wearing thin both sides (3.5.1g)

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check





Expires: 16 September 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	16 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



KM13NME report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

KM13NME

report date: 2024-03-29

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

More info >

Plate changes

ober of plates

faste since

See in this check if this PEUGEOT had different number plates.

ALS UK

UK UK

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-04-26
Last registration	2023-09-13
Complete history	See info



Registration #1	2013-04-26	24 mi
Registration #2	2016-04-11	72.725 mi
Registration #3	2017-04-29	85.791 mi
Registration #4	2018-04-30	96.868 mi
Registration #5	2018-04-30	96.868 mi
Registration #6	2019-04-23	110.063 mi
Registration #7	2019-04-24	110.063 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		0.77 44
Registration #11		9.77 es
Registration #12		0.00 44
Registration #13		11.777 es

More info >

CarCheck.co.uk page 11/12



KM13NME report date: 2024-03-29

Car features

S0225	Air conditionin
S0295	
S0482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	79%
Pedestrian	37%
Safety systems	97%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2118 mm
Height	1638 mm
Length	4530 mm
Wheel base	2728 mm
Kerb weight	1699 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/1

Number of axles 2

Engine number JBER0104213