



report date: 2024-03-28

General information

Make	MINI
Model	PACEMAN COOPER D
Colour	Silver
Year of manufacture	2014
Top speed	116 mph
0 - 60 mph	10.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 2.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	C







Internet history

Entry 1

Date	2021-12-05
Pictures	4
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-05
MOT pass rate	100 %
MOT passed	3
Failed MOT tests	0
Total advice items	14
Total items failed	0

MOT #3	2024-01-05 10:12
--------	------------------

MOT test number	111669966849
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-01-05
------------------	------------

Advice	Rear Macpherson strut corroded but not seriously weakened BOTH STRUTS (5.3.3 (b) (i))
Advice	Central Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Front Outer Nail in tyre ON OUTER EDGE
Advice	Front Oil leak, but not excessive ENGINE (8.4.1 (a) (i))
Advice	Central Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Minor	Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Front Lower Suspension arm pin or bush worn but not resulting in excessive movement BOTH LOWER ARM REAR BUSHES STARTING TO PERISH (5.3.4 (a) (i))



MOT #2 2023-01-06 12:56

MOT test number 317356631313

Result ✓ Passed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #1 2022-01-06 16:42

MOT test number 660912461038

Result ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
5 January 2025

Tax status	Valid until 1 January
Days left	248
MOT expiry date	5 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	5
First mileage registration	2014-03-19
Last registration	2024-01-05
Complete history	See info



Registration #1	2014-03-19	16 mi
Registration #2		
Registration #3	2022-01-06	86.235 mi
Registration #4		
Registration #5		

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1996 mm
Height	1518 mm
Length	4109 mm
Wheel base	2596 mm
Kerb weight	1300 kg
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Engine number	70288787
---------------	----------