





report date: 2024-03-29

## General information

Make	MAZDA
Model	3 D SE NAV
Colour	White
Year of manufacture	2015
Top speed	132 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	148 BHP
Max. torque	380 Nm at 1.800 rpm
Engine capacity	2.191 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	80.7 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/12



# Internet history

## Entry 1

Date	2021-02-01
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-08-20
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	16
Total items failed	5

MOT #9	2023-07-26 14:03
MOT test number	581196919177
Result	✓ Passed
Next expiry date	2024-08-20
Advice Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Items removed from driver's view prior to test	

MOT #8		2022-08-09 09:25
MOT test	number	727055021854
Result		✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #7		2021-07-29 12:33
MOT test	number	140733575940
Result		✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 3/12



KD15BFY

report date: 2024-03-29

MOT test number

S91751660345

Result

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #5	2020-08-12 11:31
MOT test number	827549474536
Result	✓ Passed
MOT #4	2019-08-21 10:18
MOT test number	786115615163
Result	✓ Passed
MOT #3	2019-08-21 10:18
MOT test number	462858076639
Result	<b>▼</b> Failed
Pass with rectification (ii))	Offside Windscreen wiper does not clear the windscreen effectively split (3.4 (b)
Pass with rectification (ii))	Rear Brake pad(s) less than 1.5 mm thick o/s & n/s inner and outer. (1.1.13 (a)
Pass with rectification (b) (ii))	Nearside Windscreen wiper does not clear the windscreen effectively split (3.4

CarCheck.co.uk page 4/12



MOT #2 2018-07-03 12:27

**MOT test number** 955802537996

**Result** ✓ Passed

Advice Rear inner pads look low

Advice Nearside rear tyre has a cut on inner edge no cords exposed at time of test

**Advice** Engine covers and under trays fitted

**MOT #1** 2018-07-03 11:24

MOT test number 382358378597

Result X Failed

**Advice** Offside front tyre side wall damaged no cords exposed at time of test

**Advice** Rear inner pads look low

**Advice** Nearside rear tyre has a cut on inner edge no cords exposed at time of test

**Advice** Engine covers and under trays fitted

**Fail** Offside Front Outer Tyre has a bulge, caused by separation or partial failure of its structure side wall (5.2.3 (d) (i))

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	20 August 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



faste since

KD15BFY

report date: 2024-03-29

More info >

# Owner history For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this MAZDA had different number plates. about of pliates

CarCheck.co.uk page 9/12



## Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-08-07
Last registration	2023-07-26
Complete history	See info



Registration #1	2015-08-07	14 mi
Registration #2	2018-07-03	62.110 mi
Registration #3	2018-07-03	62.110 mi
Registration #4	2019-08-21	73.054 mi
Registration #5	2019-08-21	73.054 mi
Registration #6	2020-08-12	82.437 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 esi
Registration #10		11.777 es
Registration #11		10,777 est

More info >

CarCheck.co.uk page 11/12



# Safety ratings

NCAP rating	****
Adult	93%
Children	86%
Pedestrian	65%
Safety systems	81%
Overall rating	85%
Video	see crash video



# Dimensions & weight

Width	1795 mm
Height	1450 mm
Length	4585 mm
Wheel base	2700 mm
Kerb weight	1310 kg
Max. allowed weight	1910 kg

# Additional information

Fuel tank capacity	51 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	SH 30496621

CarCheck.co.uk page 12/12