



report date: 2024-03-29

General information

Make	VAUXHALL
Model	MERIVA SE
Colour	Blue
Year of manufacture	2016
Top speed	115 mph
0 - 60 mph	11.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	118 BHP
Max. torque	200 Nm at 1.850 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg
CO2 emission	166 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-02-04
Pictures	23
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-06-17
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	15
Total items failed	2

MOT #10	2023-06-18 11:11
MOT test number	958551331439
Result	✓ Passed
Next expiry date	2024-06-17

MOT #9	2023-06-15 08:13
MOT test number	753990328213
Result	✗ Failed
MAJOR Nearside Rear Position lamp showing white light to the rear (4.2.3 (a) (ii))	

MOT #8	2023-05-19 13:20
MOT test number	965292220317
Result	✗ Failed
MAJOR Central Rear Seat belt buckle not functioning as intended (7.1.2 (d))	
DANGEROUS Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
MAJOR Nearside Rear Position lamp showing white light to the rear (4.2.3 (a) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #7** 2022-10-20 13:32**MOT test number** 214212195870**Result** ✓ Passed

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing URGENT (5.2.3 (d) (ii))

MOT #6 2022-10-20 13:32**MOT test number** 888063876954**Result** ✗ Failed

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing URGENT (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))

MOT #5 2021-09-27 14:19**MOT test number** 708326757827**Result** ✓ Passed**MOT #4** 2020-09-28 15:04**MOT test number** 350218744602**Result** ✓ Passed



MOT #3	2020-09-28 09:13
MOT test number	441295497113
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Nearside Headlamp aim too high (4.1.2 (a))

MOT #2	2020-01-13 14:01
MOT test number	392900299447
Result	✓ Passed

MOT #1	2019-10-07 12:17
MOT test number	455556050647
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2mm, worn inner edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge 3mm, worn inner edge (5.2.3 (e))



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
17 June 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	17 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 VE66NYM
Plate since	2024-03-29
Current registration	 VE66NYM
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-12-09
Last registration	2023-06-18
Complete history	See info



Registration #1	2016-12-09	9 mi
Registration #2	2019-10-07	30.350 mi
Registration #3	2020-01-13	32.760 mi
Registration #4	2020-09-28	34.215 mi
Registration #5	2020-09-28	34.215 mi
Registration #6	2020-09-28	34.215 mi
Registration #7	2020-09-28	34.215 mi
Registration #8	2020-09-28	34.215 mi
Registration #9	2020-09-28	34.215 mi
Registration #10	2020-09-28	34.215 mi
Registration #11	2020-09-28	34.215 mi
Registration #12	2020-09-28	34.215 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1486 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B14NEL -19PG0898LUH