






report date: 2024-03-29

General information

Make	CITROEN
Model	C5 PURETECH FLAIR PLUS S/S
Colour	Red
Year of manufacture	2019
Top speed	121 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption combined	44.1 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/11



LF19USV

report date: 2024-03-29

Internet history

Entry 1

Date 2022-05-25

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-03-24
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	22
Total items failed	3

MOT #5	2024-03-16 12:17
MOT test number	751600710993
Result	✓ Passed
Next expiry date	2025-03-24
Advice Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))	
Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i))	
Advice Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))	
Advice Front number plate cracked.	

MOT #4		2023-03-25 12:07
MOT test	number	245693915833
Result		✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Rear Nail in tyre	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



Advice

LF19USV

report date: 2024-03-29

MOT #3 2023-03-25 10:45 **MOT** test number 740924502128 Result × Failed **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) **Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Nearside Rear Nail in tyre Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #2

MOT test number

Result

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #1

MOT test number

672616087409

Result

X Failed

Fail Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

CarCheck.co.uk page 4/11



LF19USV

report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	24 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.		OEN
THE PARTY OF THE P		

	More info	>
Plate changes See in this check if this CITROEN had different number plates.		
Number of plates		,
Correct registration	UK UK	
Plate since		
Current registration	NK NY	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2019-03-24
Last registration	2024-03-16
Complete history	See info



Registration #1	2019-03-24	21 mi
Registration #2	2022-03-21	33.488 mi
Registration #3	2022-03-21	33.488 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



Safety ratings

NCAP rating	****
Adult	81%
Children	77%
Pedestrian	32%
Safety systems	83%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	2099 mm
Height	1670 mm
Length	4500 mm
Max. allowed weight	1940 kg

Additional information

Number of seats	5
Number of axles	2
Engine number	XVA80114339

CarCheck.co.uk page 11/11