



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 SPORT D V50
Colour	Silver
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	9.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-01
Pictures	20
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #13** 2023-01-24 10:23**MOT test number** 460184703528**Result** ✗ Failed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Nail in tyre**Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MOT #12** 2022-01-05 17:24**MOT test number** 260566144095**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**MOT #11** 2021-01-05 10:53**MOT test number** 442681811045**Result** ✓ Passed**MOT #10** 2021-01-04 14:18**MOT test number** 195547911415**Result** ✗ Failed**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Inner Tyre has a bulge, caused by separation or partial failure of its structure sidewall (5.2.3 (d) (ii))

**MOT #9** 2019-07-03 07:46**MOT test number** 452598836369**Result** ✓ Passed**MOT #8** 2019-07-02 12:54**MOT test number** 672135873990**Result** ✗ Failed**Fail** Brake pad(s) less than 1.5 mm thick BOTH FRONTS (1.1.13 (a) (ii))**Fail** Suspension arm insecure and impairing directional stability BOTH REAR LOWER WISHBONE ARMS BUSHES (5.3.3 (a) (ii))**Fail** Brake pad(s) less than 1.5 mm thick REAR BRAKE PADS (1.1.13 (a) (ii))**MOT #7** 2018-06-06 09:47**MOT test number** 477969287966**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**MOT #6** 2017-06-07 10:54**MOT test number** 600022829225**Result** ✓ Passed**MOT #5** 2016-06-21 10:33**MOT test number** 829241297437**Result** ✓ Passed**MOT #4** 2015-06-18 11:27**MOT test number** 558549565196**Result** ✓ Passed



MOT #3	2014-06-25 12:04
MOT test number	259316474409
Result	✓ Passed

MOT #2	2013-06-25 12:12
MOT test number	265396073403
Result	✓ Passed
Advice	Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2012-03-13 11:29
MOT test number	587583172095
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	WJ09VZK
Plate since	2019-03-28
Current registration	WJ09VZK
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-03-07
Last registration	2023-01-24
Complete history	See info



Registration #1	2009-03-07	28 mi
Registration #2	2012-03-13	59.557 mi
Registration #3	2013-06-25	69.615 mi
Registration #4	2014-06-25	70.687 mi
Registration #5	2015-06-18	72.582 mi
Registration #6	2016-06-21	73.618 mi
Registration #7	2017-06-07	74.744 mi
Registration #8	2018-06-06	75.261 mi
Registration #9	2019-06-06	75.261 mi
Registration #10	2020-06-06	75.261 mi
Registration #11	2021-06-06	75.261 mi
Registration #12	2022-06-06	75.261 mi
Registration #13	2023-01-24	75.261 mi
Registration #14	2023-01-24	75.261 mi
Registration #15	2023-01-24	75.261 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1489 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	521737