



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2000 CDTI
Colour	White
Year of manufacture	2008
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	240 Nm at 2.300 rpm
Engine capacity	1.686 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2021-03-22
MOT pass rate	56 %
MOT passed	10
Failed MOT tests	8
Total advice items	56
Total items failed	33

**MOT #18**

2021-03-27 14:33

MOT test number

238665124641

Result**✗ Failed**

- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Horn sound not in accordance with requirements (7.7 (c))
- Advice** Rear Seat belt buckle slightly damaged Both Cover Missing (7.1.2 (d))
- Advice** Front Number Plate Damaged
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Small Clip (6.1.7 (g) (ii))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Rear Parking (secondary brake) on a single line braking system has no recorded effort at a wheel (1.3.1 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Battery insecure and likely to cause a short circuit (4.13 (a) (ii))
- Fail** Offside Front Side repeater missing (4.4.1 (a) (ii))
- Fail** Nearside Rear Brake cable damaged Rubbing (1.1.15 (a))
- Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Central Rear Seat belt buckle missing (7.1.2 (d))
- Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps Both (4.7.1 (b) (ii))
- Advice** Play in steering rack inner joint(s)
- Fail** Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Rear Tyre worn close to legal limit/worn on edge Both On Inner Edges (5.2.3 (e))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))

**MOT #17** 2020-03-23 12:12**MOT test number** 275191289022**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Offside Front Obligatory mirror slightly loose (3.3 (b) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Coil spring corroded All 4 (5.3.1 (b) (i))**MOT #16** 2020-03-23 12:12**MOT test number** 985585489056**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Coil spring corroded All 4 (5.3.1 (b) (i))**Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Offside Front Obligatory mirror slightly loose (3.3 (b) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #15** 2019-03-18 12:03**MOT test number** 542785572928**Result** ✓ Passed**Advice** Nearside Front link slight play**Advice** Front wipers**Advice** Front number plate slightly cracked

**MOT #14** 2018-05-04 11:26**MOT test number** 212991822833**Result** ✓ Passed**Advice** Offside Parking brake lever has little reserve travel (3.1.6b)**MOT #13** 2018-05-04 11:26**MOT test number** 311244714364**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Offside Parking brake lever has little reserve travel (3.1.6b)**MOT #12** 2017-05-15 13:29**MOT test number** 736835424174**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Coil spring corroded front and rear (2.4.C.1b)**Advice** Parking brake passed on limit

**MOT #11** 2017-05-15 13:29**MOT test number** 198723254065**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**Advice** Parking brake passed on limit**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Coil spring corroded front and rear (2.4.C.1b)**MOT #10** 2016-05-19 13:18**MOT test number** 923780556393**Result** ✓ Passed**Advice** Coil spring corroded all 4 (2.4.C.1b)**Advice** Nearside Front Track rod end ball joint has slight play inner arm (2.2.B.1f)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #9** 2015-04-20 19:04**MOT test number** 667030815123**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Nearside Front Road wheel tyre ring butting but not displaced from its seating (4.2.B.1d)

**MOT #8** 2015-04-20 17:12**MOT test number** 817440315128**Result** ✗ Failed**Fail** Offside Rear Rear position lamp(s) not working (1.1.A.3b)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Nearside Front Road wheel tyre ring butting but not displaced from its seating (4.2.B.1d)**MOT #7** 2014-05-13 14:42**MOT test number** 146533834111**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #6** 2014-05-12 12:54**MOT test number** 517832934134**Result** ✗ Failed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Horn not working (1.6.2a)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Play in steering rack inner joint(s)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Fail** Front Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #5** 2013-04-26 15:24**MOT test number** 338256513198**Result** ✓ Passed**MOT #4** 2013-04-26 09:43**MOT test number** 686246513173**Result** ✗ Failed**Fail** Rear Registration plate lamp not working (1.1.C.1d)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Rear coil spring incomplete (2.4.C.1a)



MOT #3 2012-05-08 15:29

MOT test number 527769422152

Result ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #2 2012-05-08 10:29

MOT test number 137499922176

Result ✗ Failed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2011-05-04 12:13

MOT test number 535334121191

Result ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Front headlamps require attention



Tax & MOT check

✕
Untaxed

Tax expired:
4 December 2020

✕
MOT

Expired:
22 March 2021

Tax status

Expired at 4 December 2020

Days left

1242 days too late

MOT expiry date

22 March 2021

Full MOT history

[See MOT history](#)




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 YP08TJU
Plate since	2019-03-29
Current registration	 YP08TJU
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-04-30
Last registration	2021-03-27
Complete history	See info



Registration #1	2008-04-30	22 mi
Registration #2	2011-05-04	18.543 mi
Registration #3	2012-05-08	57.531 mi
Registration #4	2012-05-08	57.539 mi
Registration #5	2013-04-26	70.251 mi
Registration #6	2013-04-26	70.251 mi
Registration #7	2014-05-12	113.315 mi
Registration #8	2014-05-13	87.315 mi
Registration #9	2015-04-20	96.427 mi
Registration #10	2015-04-20	96.427 mi
Registration #11	2016-04-20	96.427 mi
Registration #12	2016-04-20	96.427 mi
Registration #13	2016-04-20	96.427 mi
Registration #14	2016-04-20	96.427 mi
Registration #15	2016-04-20	96.427 mi
Registration #16	2016-04-20	96.427 mi
Registration #17	2016-04-20	96.427 mi
Registration #18	2016-04-20	96.427 mi
Registration #19	2016-04-20	96.427 mi

More info >



Dimensions & weight

Width	1892 mm
Height	1801 mm
Length	4323 mm
Kerb weight	1453 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	1835513