



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	106 INDEPENDENCE
Colour	Blue
Year of manufacture	-
Top speed	101 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	89 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg





Internet history

Entry 4

Date	2021-07-07
Pictures	6
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 3

Date	2021-06-30
Pictures	6
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 2

Date	2021-06-21
Pictures	5
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-17
------	------------

Pictures

5

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #19</b>	2021-05-17 11:05
<b>MOT test number</b>	211559550548
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-05-16

<b>MOT #18</b>	2021-05-17 11:05
<b>MOT test number</b>	768460806162
<b>Result</b>	✗ Failed
<b>Pass with rectification</b> Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	

<b>MOT #17</b>	2020-08-07 13:51
<b>MOT test number</b>	172207790140
<b>Result</b>	✓ Passed
<b>Advice</b> Steering column top bearing slightly worn (2.2.2 (b))	

<b>MOT #16</b>	2020-08-05 14:19
<b>MOT test number</b>	570698585438
<b>Result</b>	✗ Failed
<b>Fail</b> Brake fluid contaminated (1.8 (a))	
<b>Advice</b> Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
<b>Fail</b> Rear Exhaust has a major leak of exhaust gases silencer (6.1.2 (a))	
<b>Minor</b> Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
<b>Advice</b> Steering column top bearing slightly worn (2.2.2 (b))	
<b>Fail</b> Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	

**MOT #15**

2019-03-21 15:06

**MOT test number**

101237479495

**Result**

✓ Passed

- Advice** Central Rear Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge close to limit / also perished (5.2.3 (e))
- Advice** Nearside Front Drive shaft joint worn, but not excessively outer joint (6.1.7 (c) (i))
- Advice** Nearside Rear Oil leak, but not excessive slight leak from gearbox (8.4.1 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing perished / aged . original (5.2.3 (d) (ii))
- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 29 % / also offside brake lagging slightly behind nearside (1.2.1 (b) (i))
- Advice** Front Power steering pipe/hose has slight seepage (2.1.5 (a))
- Minor** Offside Front Obligatory mirror slightly damaged glass small crack (3.3 (b) (i))

**MOT #14**

2018-03-26 11:27

**MOT test number**

889996852099

**Result**

✓ Passed

- Advice** Offside Front Obligatory mirror deteriorated, but not seriously affecting the rear view small crack in glass (8.1.2a)
- Advice** Offside Front Front constant velocity joint is slightly worn (2.5.C.1b)
- Advice** Nearside Front Body has slight corrosion bumper inner support bracket corroded and weak (6.1.B.2)
- Advice** Central Front Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear mounting (2.4.G.2)

**MOT #13**

2017-03-20 13:09

**MOT test number**

451220001892

**Result**

✓ Passed

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear mounting starting to separate (2.4.G.2)

**Advice** Front Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)

**Advice** Offside Front Obligatory mirror damaged, but not seriously affecting the rear view small crack in glass (8.1.2a)

**Advice** Offside Front Front constant velocity joint is slightly worn (2.5.C.1b)

**Advice** Nearside Rear Tyre worn close to the legal limit close on outer tread (4.1.E.1)

**MOT #12**

2016-03-23 13:54

**MOT test number**

884206505626

**Result**

✓ Passed

**Advice** Offside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

**Advice** Nearside Front Front constant velocity joint is slightly worn (2.5.C.1b)

**Advice** Nearside Front Tyre worn close to the legal limit wearing on outer tread (4.1.E.1)

**Advice** Offside Front Front constant velocity joint is slightly worn (2.5.C.1b)

**MOT #11**

2015-03-16 12:01

**MOT test number**

186695375493

**Result**

✓ Passed

**Advice** Offside Front Front constant velocity joint is slightly worn (2.5.C.1b)

**Advice** Offside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

**Advice** Front Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)

**MOT #10**

2014-03-17 14:19

**MOT test number**

868956274076

**Result**

✓ Passed

**MOT #9** 2014-03-17 11:43**MOT test number** 785966274091**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #8** 2013-03-18 10:28**MOT test number** 456327873087**Result** ✓ Passed**Advice** Front Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)**Notice** Nearside front wiper blade slightly torn on end**Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #7** 2012-03-07 10:42**MOT test number** 537957462017**Result** ✓ Passed**MOT #6** 2011-03-14 10:15**MOT test number** 406723071088**Result** ✓ Passed**Notice** Slight oil leak to nearside front drive shaft diff oil seal**Advice** Centre Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**Notice** Nearside front wiper blade slight tear to rubber

**MOT #5** 2010-03-16 11:43**MOT test number** 330305770048**Result** ✓ Passed**Advice** Centre Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Offside front and nearside rear tyres slightly perished in treads**MOT #4** 2009-03-09 09:30**MOT test number** 604338969020**Result** ✓ Passed**MOT #3** 2008-03-10 12:30**MOT test number** 411640478058**Result** ✓ Passed**MOT #2** 2007-03-14 12:33**MOT test number** 914653977085**Result** ✓ Passed**MOT #1** 2006-03-20 11:25**MOT test number** 243239776023**Result** ✓ Passed





Damage history


Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>BJ03TXZ</b>
Plate since	2024-03-29
Current registration	<b>BJ03TXZ</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-03-29
Last registration	2021-05-17
Complete history	<a href="#">See info</a>



Registration #1	2003-03-29	15 mi
Registration #2	2006-03-20	14.877 mi
Registration #3	2007-03-14	19.253 mi
Registration #4	2008-03-10	24.675 mi
Registration #5	2009-03-09	31.930 mi
Registration #6	2010-03-16	37.743 mi
Registration #7	2011-03-14	44.471 mi
Registration #8	2012-03-07	52.788 mi
Registration #9	2013-03-18	61.228 mi
Registration #10	2014-03-17	67.263 mi
Registration #11	2014-03-17	67.263 mi
Registration #12	2015-03-16	72.690 mi
Registration #13	2016-03-16	78.117 mi
Registration #14	2017-03-16	83.544 mi
Registration #15	2018-03-16	88.971 mi
Registration #16	2019-03-16	94.398 mi
Registration #17	2020-03-16	99.825 mi
Registration #18	2021-03-16	105.252 mi
Registration #19	2022-03-16	110.679 mi
Registration #20	2023-03-16	116.106 mi
Registration #21	2024-03-16	121.533 mi
Registration #22	2025-03-16	126.960 mi
Registration #23	2026-03-16	132.387 mi
Registration #24	2027-03-16	137.814 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1594 mm
Height	1357 mm
Length	3678 mm
Wheel base	2385 mm
Kerb weight	815 kg
Max. allowed weight	891 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Single-Point Injection
Number of doors	3
Number of axles	2
Engine number	FP6T4220799