



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX20 STYLE
Colour	Black
Year of manufacture	2011
Top speed	114 mph
0 - 60 mph	12.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	123 BHP
Max. torque	156 Nm at 4.200 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	154 g/km
CO2 label	G





## Internet history

### Entry 3

Date 2021-07-30

Pictures 6

Listing price [View report](#)




source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 2

Date 2021-07-29

Pictures 6

Listing price [View report](#)




source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 1

Date 2021-06-15

Pictures 7

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-22
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	60
Total items failed	3

MOT #13	2023-06-23 16:54
MOT test number	203758926781
Result	✓ Passed
Next expiry date	2024-06-22
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Rear Brake pipe corroded, covered in grease or other material Both sides (1.1.11 (c))
Advice	Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #12**

2023-06-21 15:47

**MOT test number**

502817188857

**Result****✗ Failed**

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre has a slight bulge on inner side wall
- Advice** Offside Front Nail in tyre
- MAJOR** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Nail in tyre
- Advice** Rear Brake pipe corroded, covered in grease or other material Both sides (1.1.11 (c))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #11**

2022-05-24 08:28

**MOT test number**

971488743249

**Result**

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge both sides inner tread (5.2.3 (e))
- Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material both sides (1.1.11 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10**

2021-05-01 10:18

**MOT test number**

708706675790

**Result**

✓ Passed

- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule front rear flexi hard pipe corroded (1.1.12 (f) (i))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Heat shield insecure rear
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material rear of front to rear corroded (1.1.11 (c))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule front rear flexi hard pipe corroded (1.1.12 (f) (i))

**MOT #9** 2021-04-27 11:00**MOT test number** 278636943918**Result** ✗ Failed**MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Heat shield insecure rear**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Nearside Rear Brake hose has slight corrosion to ferrule front rear flexi hard pipe corroded (1.1.12 (f) (i))**MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MAJOR** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MAJOR** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material rear of front to rear corroded (1.1.11 (c))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Brake hose has slight corrosion to ferrule front rear flexi hard pipe corroded (1.1.12 (f) (i))**MOT #8** 2020-05-21 09:11**MOT test number** 760203502351**Result** ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material corroded. (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material corroded. (1.1.11 (c))

**MOT #7** 2019-05-09 13:02**MOT test number** 423263789804**Result** ✓ Passed**Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #6** 2018-05-14 08:26**MOT test number** 913061761466**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2017-05-22 16:05**MOT test number** 595290856795**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #4** 2017-05-19 09:52**MOT test number** 821098159414**Result** ✗ Failed**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Items removed from driver's view prior to test**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #3	2016-04-21 10:59
MOT test number	116792465397
Result	✓ Passed
Advice	Offside Rear coil spring corroded (2.4.C.1b)
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #2	2015-09-16 08:31
MOT test number	258349858581
Result	✓ Passed
Advice	All 4 tyre tread cracked/splitting through centre of treads

MOT #1	2014-08-27 12:40
MOT test number	729279634223
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
22 June 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	22 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-09-22
Last registration	2023-06-23
Complete history	<a href="#">See info</a>



Registration #1	2011-09-22	6 mi
Registration #2	2014-08-27	11.285 mi
Registration #3	2015-09-16	15.804 mi
Registration #4	2016-04-21	17.544 mi
Registration #5	2017-05-19	27.190 mi
Registration #6	2017-05-22	27.190 mi
Registration #7	2018-05-14	35.781 mi
Registration #8	2019-05-09	45.459 mi
Registration #9	2020-05-21	55.392 mi
Registration #10	2020-05-21	55.392 mi
Registration #11	2020-05-21	55.392 mi
Registration #12	2020-05-21	55.392 mi
Registration #13	2020-05-21	55.392 mi
Registration #14	2020-05-21	55.392 mi
Registration #15	2020-05-21	55.392 mi
Registration #16	2020-05-21	55.392 mi
Registration #17	2020-05-21	55.392 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1294 kg
Max. allowed weight	1730 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	G4FCAZ212710